

Part 1: Applied Machining Word Problems (1–9)

1. **B. R plane**
 2. **B. 0.995 to 1.005**
 3. **B. Flatness**
 4. **A. Yes**
 5. **C. ~0.332**
 6. **A. G83**
 7. **B. Mislocated features**
 8. **B. Vibration and deflection**
 9. **C. Tool length offset applied**
-

Part 2: GD&T (10–18)

10. **B. Maximum Material Condition – smallest hole/largest pin**
11. **A. Form is absolute; orientation is relative to a datum**
12. **C. \perp**
13. **B. The exact location of a feature within a tolerance zone**
14. **C. Surface plate with height gauge**
15. **C. Surface controls all points; line controls a cross-section**
16. **C. It applies location and orientation together**
17. **B. CMM is 3-axis capable and programmable**
18. **B. Regardless of Feature Size**

Part 3: Decimal Lingo & Shop Math (19–27)

19. **C. Five thousandths**
 20. **A. Thirty ten-thousandths**
 21. **B. 0.1**
 22. **A. 0.005 to 0.015**
 23. **C. One tenth, one hundredth, one thousandth**
 24. **A. 253**
 25. **B. Yes**
 26. **A. 9**
 27. **B. 11**
-

Part 4: Decimal Conversion (28)

28. **C. 0.05**
-

Part 5: Milling Machine Components (29–33)

29. **C. Spindle**
30. **A. Table**
31. **C. Saddle**
32. **D. Knee**
33. **C. Quill**

Part 6: Vocabulary Review (34–38)

34. **C. Angularity**

35. **B. Datum**

36. **B. Blueprint**

37. **D. Tolerance**

38. **B. Chamfer**