
Q_{IT} = 10 kW
TCS boundary
$\dot{m}_i$, K_i
$T_{h,i}$, UA_i
B1
B2
B3
B4
Q_a = 2 kW
residual air
T_s, $\dot{m}$
CDU and facility loop (excluded)
$Q_\ell = f_\ell Q_{IT}$ = 8 kW
T_r
boundary signal
M3 branch state