Inspection Report Excerpt

RE-002 drainage and foundation review

Foundation Finding

Inspection flags patio runoff toward the foundation after heavy rain.

Risk Level

Repair should be verified before the buyer treats the listing as turnkey.

Comparison Note

Canyon Lane packet is cleaner but costs more; recommendation depends on tolerance for hidden work.