


Implied yaw floor before and after the August repair

● Borrowed calibration ◆ After φ repair

Dive 60 $\leftarrow$ 65 $\varphi = -0.1458^\circ$



Dive 76 $\leftarrow$ 63 $\varphi = -0.1505^\circ$

