

A flat port's error follows the field angle, not the lens

