
What limits “exact by construction” is assembly, not specification
A constant we only think we know
recovered fx error (%)
0.0
−0.5
−1.0
−1.5
−2.0
0.10
0.15
0.20
0.25
0.30
true chamfer (mm), model assumes 0.25
How well it is built
recovered error (%)
0.0
−0.5
−1.0
−1.5
−2.0
fx
fx/fy ratio
0.00
0.05
0.10
0.15
0.20
per-brick placement error (mm, sd)