



Power Input & Filtering




Laser Driver Input



Laser Output Connections




Signal Prep and PECL Translation




Laser 1 Driver (Inverting)

See datasheet for R_MODSET value selection and jumper usage. Two resistors placed for R_MODSET intended for footprint flexibility.




Laser 0 Driver (non-Inverting)


See datasheet for R_MODSET value selection and jumper usage. Two resistors placed for R_MODSET intended for footprint flexibility.



PECL Termination



PECL Termination



See <https://www.mouser.com/pdfDocs/peclclocksandtermination.pdf> for PECL termination

Engineer: Dylan Hu
Reviewing Engineer: Graydon SK
UChicago Space Program

Sheet: /
File: LaserDriver.kicad_sch

Title: Laser Driver

Size: USLetter Date: 2026-02-01
KiCad E.D.A. 9.0.7

Rev: v0.1
Id: 1/1