## Cuts for Panel #0 test

This file appears mirrored, as viewed from the rear Red dots are pilot holes drilled 1/2" deep only, not penetrating front surface

