

MAINDEC CHANGE NOTICE

Ø8-DIGD-1 CHANGE NO.

Sheet 1 of 1

AUTHOR
John Vrobel
DATE EXT.

PROGRAM DATE

PRODUCT LINE

MAINDEC NUMBER

DATE EXT. 6/16/72 3621

7/27/7Ø

8

Ø8-D1GD

PROGRAM NAME PDP8,81,85 Extended
Memory Control

DEVICE Extended Memory Control

ITEM

1. 6/16/12 Problem:

The error detection in the "INTERRUPT INHIBIT TEST"

is incorrect.

Correction: Change LOCATION 1305 from 5312 to 5010.

Correction: Change LOCATION 1313 from 5307 to 5005.

oriented to the

OFA 7.13451-1136.N17