5 locations congeston tape "MAINT #1" Nov 12, 16

loc	was on Tap.	corrected re: listing
2203	2411	2415
2227	1011	1015
2237	0412	0416
2247	3012	3016
2257	1030	1034

IDENTIFICATION

Product Code:

MAINDEC-8I-D02B-D

Product Name:

Instruction Test 2

Date Created:

March 21, 1968

Maintainer:

Diagnostic Group

Author:

H. Horowitz



C

1. ABSTRACT

This program is an extensive test of autoindexing, indirect addressing, and the DCA instruction for the PDP-8I. It also offers minimal testing for interrupt and the AND, TAD, ISZ, JMP and JMS instructions.

2. REQUIREMENTS

2.1 Equipment

PDP-8I, 8S equipped with Teletype

2.2 Storage

The program occupies memory locations 0000-4021. The Binary Loader must be stored in the last memory page.

2.3 Preliminary Programs

It is assumed that Maindec 8I-D01(n) has been run successfully.

LOADING PROCEDURE

3.1 Method

The standard Binary Loader is used.

4. STARTING PROCEDURE

4.1 Control Switch Settings (None)

4.2 Starting Address

201

4.3 Operator Action

- a. Set the SWITCH REGISTER to 201. Press LOAD ADDRESS.
- b. PUSH START. A programmed halt occurs when an error is encountered.

5. OPERATING PROCEDURE

Same as Section 4.

6. ERRORS

6.1 Error Halts and Description

See listing.

6.2 Error Recovery

If it is desired to loop on the test causing the error, replace the operate instruction preceding the HLT with a JMP to the beginning of the test.

7. RESTRICTIONS

All peripheral devices must be functioning to a degree that the processor START button will clear their flags and no FLAGS will turn on unless authorized.

8. MISCELLANEOUS

8.1 Execution Time

Five program loops per second.

9. PROGRAM DESCRIPTION

The program is a series of many small individual tests. Each test is performed using previously checked functions to validate the test. When an error is encountered, the operator should insert a jump instruction into memory to cause the program to loop on the failing test. The problem can then be found by using the oscilloscope.

The individual program tests are grouped into the following classifications and are performed in the order shown:

- 1. DCA Test
- 2. Indirect Addressing Test
 - a. using TAD
 - b. using AND

- 3. Autoindex Test
 - a. using AND
 - b. using DCA
 - c. using TAD
- 4. Interrupt Test
 - a. following NOP
 - b. following TAD
 - c. following AND
 - d. following DCA
 - e. following ISZ
 - f. following JMP
 - g. following JMS
 - h. following CLA
 - i. following TSF
- 5. Check for unauthorized Autoindexing

At the completion of 40 program loops the bell rings to assure the operator that the program is functioning properly.

10. LISTING

.

L

/INSTRUCTION TEST 2

	0000	*0			
~ ~ ~ ~	-	₩₽	•		4.65.5
0000			0	_	/LOC Ø
0001			JMP 1	/LOC	1
0002	0002		2	/LOC	2
0003	0003		3	/L0¢	3
					•
	0007	* 7			
0007	-	~ ,	Ø		
000/	2000		· ·		
	0000	. 0.7			
	0020	*20			
0020	7777	K7777,			
0021	· 3777	K3777.			
0022	577 7	K5777,			
0023	6777	K6777,	67 <i>‡</i> 7		
0024	7377	K7377,	7377		
0025	7577	K7577.	7577		
0026	7677	K7677.			
0027	7737	K7737.	7737		
_		K//3//			
0030	0000	W	0		
0031	7757	K7757,	7777		
0032	7767	K7767,			
ØØ33	7773	K7773,	7773		
0034	7775	K7775,	7775		
0035	7776	K7776,	77#6		
0036	0000	KØ,	Ø		
0037	1777	K1777,	1777		
0040	Ø777	K0777,	0717		
0041	0377	KØ377,	03/7		
0042	0177	KØ177,	01/7		
0043	0077	KØ077,	0077		
0044	0037	KØØ37,	0037		
0045	0017	KØ017.	0047	•	
0046	0007	KU007.	0007		
0047	0003	K0003.	0003		
0050	0000		Ø		
0051	0001	K0001,	00×1		
0052	4400	K4400,	4400		
0053	4577	K4577,	45 # 7		
0054	2525	K2525,	2525		
0055	6666	K66 66 ;	6606		
0056	4444	K4444,	4444		
0057	7070	K7070.	7070		
0060	0707	K0707.	0707		
0061	5252	K5252,	52#2		
0062	1111	K1111,	1111		
0063	5252	K5555,	5272		
0064	0004		4		
\$0 KD CD 44	דששש	K4,	~		

	0110	*110		
Ø110	0000		Ø	
	0172	*172		
Ø172	0176	K176,	176	/LOC 172
		K172,	174	/173
0173 0174	ø172 Ø173	K173.	175	/174
0175	0174	K174,	174	/175
0176	0175	K175,	179	/176
0170	1274	K1234	1204	/177

0200	0200 0000	*2&0 TP2,	ø		
0200	6000	1 * 0 }	v		
		/UCA	TEST 1		
0201	7200		CLA		
Ø2Ø2 Ø2Ø3	1052 3377			K4400 TP177	
Ø2Ø3	7440		SZA	11.7.	
0205	7402		HLT		/DCA DID NOT CLEAR AC
0206	1052			K4400	
0207	7410		SKP		
0210 0211	0000 7041		c ₁		/AC==(4400)
0212	1377		TAU	TP177	AC . A.A.
0213	7440		SZA	•	
0214	7402		HLT		/DCA FAILED
					AC SHOULD EQUAL ZERO
		/DCA	TEST 4		
0215	7200		CLA		
Ø216	1053	•		K4577	
0217	3200			TPØ	
Ø22Ø Ø221	7440 7402		A S Z A		/DCA DID NOT CLEAR AC
Ø222	1053			K4577	Apon Bin was offere an
Ø223	7041		ĊI"		
0224	1200			TPØ	
Ø225 Ø226	7440 7402		SZ:		ADOM EATLED
W 2 2 0	7762		™ . '		/DCA FAILED /AC SHOULD EQUAL ZERO
		/DCA	1EST 3		
0227	7200		CLA		
0230	1020			K7777	
0231	3200		DCA	TPØ	
Ø232	7440		S≠#		ADDA DAD MOT BURLD AS
Ø233 Ø234	74Ø2 12ØØ		HLI	TPØ	/DCA DID NOT CLEAR AC
0235	7040		CMA	ורט	
Ø236	7440		SZA		
0237	7402		HL!		/UCA FAILED
					/AC SHOULD BE ZERO
		/DCA	TEST 4		
0240	7200		CLA		
0241	1036		TAU		
0242	3200		DCA	TPØ	.0CA 0.10 0.5Ac AC
0243 0244	7440 7402		SZA HLI		JUCA DID NOT CLEAR AC
Ø244 Ø245	1200		TAL	TPZ	
				-	

22/6 5143,13	PAGE	4
--------------	------	---

		-	
ansa	700.4	C A	
0250	7200	CLA	
0251	1054	TAD K2525	
0252	3200	DC TPØ	
Ø253	7440	S Z A	
0254	7402	HL!	/UCA DID NOT CLEAR AC
Ø255	1054	TAU K2525	
0256	7041	CI#	
Ø257	1200	TAU TPØ	
0260	7440	S₹#	
0261	7402	H L !	/DCA FAILED
•	-		/AC SHOULD BE ZERO
		/DCA TEST 9	
	76 - 0	-1.	
0262	7200	CLA	
0263	1055	TAD K6666	
0264	3200	DC4 TPØ	
ø265	7440	SZA	
0266	7402	HLT	/DCA DID NOT CLEAR AC
0267	1055	TAD K6666	
0270	7041	CIA	
Ø271	1200	TAU TPØ	
Ø272	7440	SZA	
g 273	7402	HLT	/UCA FAILED
	D		/AC SHOULD BE ZERO
		/DCA TEST 7	
0274	7200	CLA	
Ø275	1056	TA- K4444	
0276	3377	DCA TP177	
0277	7440	SZA	
0300	7402	HL!	/UCA DID NOT CLEAR AC
0301	1056	TA K4444	
0302	7041	CIA	
0303			
	1377	TAP TP177	
0304	1577 7440	TAP TP177 S24	
0304 0305	7440	SZM	ZDCA FAILED
0304	•		/DCA FAILED
-	7440	SZM	/DCA FAILED /AC SHOULD BE #ERO
-	7440	SZM	
-	7440	S## HL!	
-	7440	SZM HL! /DCA TEST 8 CLA	
Ø3Ø5 Ø3Ø6 Ø3Ø7	7440 7402	SZM HL! /DCA TEST 8	
Ø3Ø5 Ø3Ø6	7440 7402 7200	SZM HL! /DCA TEST 8 CLA	
Ø3Ø5 Ø3Ø6 Ø3Ø7	7440 7402 7200 1057	SZM HL! /DCA TEST 8 CLA TAP K/0/0	
0305 0306 0307 0310	7440 7402 7200 1057 3377	SZM HL! /DCA TEST 8 CLA TAP K/0/0 DCA TP1/7	
0305 0306 0307 0310 0311	7440 7402 7200 1057 3377 7440	SZM HL! /DCA TEST 8 CLA TAP K/Ø/Ø DCA TP177 SZA	/AC SHOULD BE ≇ERO
0305 0306 0307 0310 0311 0312	7440 7402 7200 1057 3377 7440 7402	SZM HL! /DCA TEST 8 CLA TAP K/0/0 DCA TP177 SZA HL! TAU K/0/0	/AC SHOULD BE ≇ERO
0305 0306 0307 0310 0311 0312 0313	7440 7402 7200 1057 3377 7440 7402 1057	SZM HL! /DCA TEST 8 CLA TAP K/Ø/Ø DCA TP1/7 SZA HL!	/AC SHOULD BE ≇ERO
0305 0306 0307 0310 0311 0312 0313 0314	7440 7402 7200 1057 3377 7440 7402 1057 7041	SZM HL! /DCA TEST 8 CLA TAP K/0/0 DCA TP177 SZA HL! TAU K/0/0 CI- TAU TP1/7	/AC SHOULD BE ≇ERO
0305 0306 0307 0310 0311 0312 0313 0314 0315	7440 7402 7200 1057 3377 7440 7402 1057 7041 1377	SZM HL! /DCA TEST 8 CLA TAP K/0/0 DCA TP177 SZA HL! TAU K/0/0 CI~	/AC SHOULD BE ≇ERO

/DCA TEST 5

		/DCA TEST 9	
2329 2321 2322 2323	7200 1060 3000 7440	CLA TAU KØ707 DCA Ø S₹	
0324 0325 0326	7402 1060 7041	HL! TAD KØ7Ø7 CIA	/DCA DID NOT CLEAR AC
0327 0330 0331	1000 7440 7402	TA Ø SZA HL↓ /DCA [EST 10	/UCA FAILED /AC SHOULD BE ZERO
		ANDM 1621 IN	
0332 0333 0334 0335	7200 1061 3000 7440	CLA TAD K5252 DC# 0 SZA	
Ø336 Ø337 Ø34Ø Ø341	7432 1061 7041 1000	HLI TAU KD252 CIA TA- R	/DCA DID NOT CLEAR AC
0342	7444 7402	SZA HL1	/DCA FAILED /AC SHOULD BE ZERO
		/OCA TEST 11	
0344 0345 0346	7200 1062 3000	CLA TAW K1111 DCA &	
0350 0351	7440 7402 1062 7041	SZA HL! Tau <1111 C!a	/DCA DID NOT CLEAR AC
	1000 7440 7402	TAU & SZA HLT	/DCA FAILED /AC SHOULD BE ZERO
		/DCA TEST 12	
2356 2357 2360	7200 1063 3000	CLA Tau kj5j5 DCA Ø Sž#	
ช362 ช363 ช364	7440 7402 1063 7041 1000	HLI TAU KOSOO CI# TAD 2	/DCA DID NOT CLEAR AC
	7440 7432	S#A HL!	/DCA FAILED /AC SHOULD BE ZERO

,

```
*420
     0400
                        /INDIRECT ADDRESSING TEST 1
0400 7200
                                CLA
                                TAU 1 KU177
                                              /OPERAND=1234
0401 1442
                                CI"
0402 7041
                                TA+ K1234
0403 1177
                                SZA
0404 7440
                                               /TAD INDIRECT FAILED
                                HLI
0405 7402
                                               /AC SHOULD BE ZERO
                        /INDIRECT ADDRESSING TEST 2
                                CL#
0406 7200
                                SKF
0407 7410
0410 0000
                                Ø
                                TAM K7777
0411 1020
0412 0442
                                AND I KØ177
                                              /OPERAND=1234
                                CIA
0413 7041
                                TAU K1234
0414 1177
                                SZ4
0415 7440
                                HL1
                                               /AND INDIRECT FAILED
0416 7402
                                               /AC SHOULD BE ZERO
                        /INDIRECT ADDRESSING TEST 3
                                CLA
0417 7200
                                TAU K7777
0420 1020
                                DCA Ø
0421 3000
                                ISE I KØ
0422 2436
                                                /ISZ FAILED, NO SKIP
                                HL1
0423 7402
                                TAD Ø
0424 1000
                                SZA
0425 7440
                                               /ISZ INDIRECT FAILED
                                HLI
0426 7402
                                               /AC SHOULD BE Ø
                        /INDIRECT #UDRESSING TEST 4
                                CLA
0427 7200
                                TAU 1 K176
                                               /OPERAND=175
0430 1572
                                CIA
Ø431 7041
                                TAU K175
0432 1176
0433 7440
                                SZA
                                               /TAD INDIRECT FAILED
                                HLT
0434 7402
                                               /AC SHOULD BE ZERO
```

```
CLA
   2435 720€
                                    TAN K7777
   2436 1220
                                    ANU 1 K176
                                                   /OPERAND=175
____0437 Ø572
                                    CIA
   0440 7041
                                    TAU K175
   0441 1176
                                    SZA
                                                   /AND INDIRECT FAILED
   0442 7440
                                                   /AC SHOULD BE ZERO
                                    HL!
   0443 7402
                           /INDIRECT ADDRESSING TEST 6
                                    CLA
   0444 7200
                                    TA- K176
   0445 1172
                                    DCA Ø
   0446 3000
                                  · ISE I KO
   0447 2436
                                    SKP
   0450 7410
                                                   /ISZ SKIPPED ILLEGALLY
   0451 7402
                                    HL
   0452 1002
                                    TAD Ø
   0453 7041
                                    CIA
                                    TAN K176
   0454 1172
   0455 7040
                                    CMA
   0456 7440
                                    SZ#
                                                   /UCA INDIRECT FAILED
                                    HLT
   0457 7402
                                                   /AC SHOULD BE ZERO
                           /INDIRECT ADDRESSING TEST 7
                                    CLA
   0460 7200
                                                   /UPERAND=176
   0461 1573
                                    TAD 1 K172
   0462 7041
                                    CIA
                                    TAU K176
   0463 1172
   0464 7440
                                    SZ*
                                               TAU INDIRECT FAILED
   0465 7402
                                    HLI
                                                   /AC SHOULD BE ZERO
                           /INDIRECT ADDRESSING TEST 8
                                    CLA
   2466 7200
                                   TAU K7777
   0467 1020
                                                   /OPERAND#176
                                    AND 1 K172
   0470 0573
                                    CIA
   0471 7041
                                    TAD K176
   Ø472 1172
                                    SZA
                                                   /AND INDIRECT FAILED
   0473 7440
                                    HL!
                                                   /AC SHOULD BE ZERO
   0474 7402
```

/INDIRECT ADDRESSING TEST 5

1/22/6 5:43,17 PAGE 9

		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
0.435	7000	CLA	
0475	7200	TAU K172	
2476	1173	DC ?	
0477	3002	ISZ I KU	
0500	2436	SKH.	
0501	7410		i V
0502	7402	·	
0503	1000	TAD 0	
2504	7041	CIA	
0505	1173	TA# K172	
0506	7040	CM#	
0507	7440	SZ*	
0510	7402	HLT /UCA INDIRECT FAILED	
		/AC SHOULD BE ZERO	
		/INDIRECT ADDRESSING TEST 10	
		CL A	
0511	7200		
0512	1574	• • • • • • • • • • • • • • • • • • • •	
•	7041	CIA	
0514	1173	TAD K172	
2515	7440	52# 	,
0516	7402	HL4 /TAD INDIRECT FAILED	,
		/AC SHOULD BE ZERO	
		/INDIRECT ADDRESSING TEST 11	
Ø5 1 7	7200	CLA	
Ø52Ø	1020	TAN K7777	
	0574	AND I K173 /OPERAND=172	
	7041	CIA	
	1173	TAU K172	
•		SZA /AND INDIRECT FAILED)
-	7440	HLI /AC SHOULD BE ZERO	
Ø525	7402	ME.	
		/INDIRECT ADDRESSING TEST 12	
Ø526	7200	CLA	
0527	1174	TAD K173	
0530	3000	DCA &	
2531	2436	IST I KO	
Ø532	7410	SKP	
Ø533	7402	HLT /152 SKIPPED ILLEGAL	LY
2534	1000	TAD P.	
2534 2535	7041	CIA	
	_	TAU K173	
0536	1174	CWA	
2537	7040	S £ A	
2540	7440	HLI /UCA INDIRECT FAILED)
0541	7402	/AC SHOULD BE PERO	
		AND SHOULD BE REND	

/INDIRECT ADDRESSING TEST 9

/INDIRECT ADDRESSING TEST 13

Ø542	7200	CLA	~
0543	1575	TAU K174 /OPERAND=173	
2544	7041	CIA	
0545	1174	TAW K173	
0546	7440	SZA	
0547	7402	HLT /TAD INDIRECT FA /AC SHOULD BE ZE	
		/INDIRECT ADDRESSING TEST 14	
Ø55Ø	7200	CLM	
Ø551	1020	TAU K7777	
0552	0575	AND 1 K174 /OPERAND=173	
Ø553	7041	CIA	
0554	1174	TAU K175	
Ø555	7440	SZA /AND INDIRECT FA	ILED
0556	7402	HLI /AC SHOULD BE ZE	RO
		/INDIRECT ADDRESSING TEST 15	
Ø557	7200	CLA	
0560	1175	TA K174	
Ø561	3000	DCA Ø	
0562	2436	is≠ i kø	
0563	7410	SK∺	
Ø564	7402	HL: /ISZ SKIPPED ILL	EGALLY
Ø565	1000	TAL Ø	
Ø566	7041	CIA	
0567	1175	TAN K174	
0570	7040	CM	
0571	7440	SZA	
Ø572	7402	HLI /DCA INDIRECT F	
		/AC SHOULD BE ?E	RO
Ø573	5377	JMF .+4	
Ø574	7000	NOF	
Ø575	7 2 0 0	NOF	
0576	7000	NO	
3577	7000	NOP	

Ø6 Ø Ø	*600 /INDIRECT ADDRESSING	TEST 16
0600 7200 0601 1576 0602 7041 0603 1175	CLA TAD I K175 CIA TAD K174	/OPERAND=174
Ø6Ø4 7440 Ø6Ø5 7432	HΓ † 25 ·	/TAD INDIRECT FAILED /AC SHOULD BE ₹ERO
	/AUTO INDEX TEST 1	
0606 7200 0607 1036 0610 3010 0611 0410	CL" TAU KØ DCA 10 ANU I 10	/CONSTANT TO BE INDEXED /DO AUTO INDEX
0612 1010 0613 1035	TAU 10 TAD K7776 CMA	/AC SHOULD EQUAL 7777
0614 7042 0615 7440 0616 7402	SZA HLT	∕AC SHOULD BE ₹ERO ∕AUTO INDEX ERROR
	/AUTO INDEX TEST 2	
0617 7200 0620 1035 0621 3010 0622 0410 0623 1010 0624 1036 0625 7042 0626 7440 0627 7402	CLA TAU K7776 DC# 10 AN- I 10 TAU 10 TAD K0 CMA SZ HL!	/CONSTANT TO BE INDEXED /DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR
	/AUTO INDEX TEST 3	
Ø63Ø 72ØØ Ø631 1034 Ø632 3012 Ø633 3410 Ø634 1212 Ø635 1251 Ø636 7240 Ø637 7440 Ø640 7422	CLA TAD K/775 DCA 10 DCA I 10 TAC 10 TAC 10 TAC 10 TAC K0001 CMA SZA HLT	/CONSTANT TO BE INDEXED /DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR
	VAUTO INDEX TEST 4	
0641 7280 0642 1233 0643 3919 0644 1418 0645 7288 2646 1818	CLA TAU K7773 DC: 10 TAU I 10 CLA TAU 10	/CONSTANT TO BE INDEXED

1/22/68 15:43,24 PAGE 11-1

/AC SHOULD EQUAL 7777 TAU K0003 0647 1047 0650 7040 0651 7440 0652 7402 CMA /AC SHOULD BE ZERO /AUTO INDEX ERROR SZA HLT

		/AUTO INDE	X TEST 5	
2653	7200	ÇĻ		/CONSTANT TO BE INDEXED
2654	1632		⊌ K7767 A 1 [©]	ACOMBINAL TO BE IMPENTED
2655	30 ₁ 2 0410		D 1 10	/DO AUTO INDEX
Ø656 Ø657	1010	TA		, 00 x010 : x02x
2660	1246		D K0007	/AC SHOULD EQUAL 7777
Ø661	7040	CM	-	• • • • • • • • • • • • • • • • • • • •
Ø662	7440	SZ	A	/AC SHOULD BE ZERO
0663	7402	HL	1	/AUTO INDEX ERROR
		/AUTO INDE	A TEST 6	
Ø664	7200	CL		
0665	1031		D K7757	/CONSTANT TO BE INDEXED
Ø665	3010	- 1	A 10	ADD AUTO INDEV
Ø667	0410		W I 10	/DO AUTO INDEX
Ø67Ø	1010		J 10 H K0317	/AC SHOULD EQUAL 7777
0671	1045	C M		AC BUDGED ERONE ////
Ø672 Ø673	7040 7440	C™ S≇		/AC SHOULD BE ZERO
Ø674	7402	HL		AUTO INDEX ERROR
		/AJTO INDE	A TEST 7	
2675	7200	/AJTO INDŁ		
2675 2676	7200 1027	CL TA	A D k7737	CONSTANT TO BE INDEXED
	1027 3010	CL TA DC	A D k7737 # 10	•
0676 0677 0700	1027 3010 0410	CL TA DC AN	A D k7737 # 10 D I 10	/CONSTANT TO BE INDEXED
0676 0677 0700 0701	1027 3010 0410 1010	CL TA DC AN TA	A D k7737 A 10 D I 10 D 10	/DO AUTO INDEX
0676 0677 0700 0701 0702	1027 3010 0410 1010 1044	CL TA DC AN TA TA	A D K7737 A 10 D I 10 D 10 U K0037	•
0676 0677 0700 0701 0702 0703	1027 3010 0410 1010 1044 7040	CL TA DC AN TA TA	A D K7737 A 10 D I 10 D 10 U K0037 A	/DO AUTO INDEX /AC SHOULD EQUAL 7777
0676 0677 0700 0701 0702	1027 3010 0410 1010 1044	CL TA DC AN TA TA	A D K7737 A 10 D I 10 D 10 U K0037 A	/DO AUTO INDEX
0676 0677 0700 0701 0702 0703 0704	1027 3010 0410 1016 1044 7046 7440	CL TA DC AN TA TA CM SZ	A D K7737 A 10 D I 10 D 10 D 10 D 10 A	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO
0676 0677 0700 0701 0702 0703 0704 0705	1027 3010 0410 1010 1044 7040 7440 7402	CL TA DC AN TA TA CM SZ HL	A D K7737 A 10 D I 10 D 10 D 10 D K0037 A	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO
0676 0677 0700 0701 0702 0703 0704 0705	1027 3010 0410 1012 1044 7042 7440 7402	CL TA DC AN TA TA CM SZ HL /AUTO INDE	A D K7737 A 10 D I 10 D 10 D 10 D K0037 A	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR
0676 0677 0700 0701 0702 0703 0704 0705	1027 3010 0410 1010 1044 7040 7440 7402	CL TA DC AN TA TA CM SZ HL /AUTO INDE TA	A D k7737 A 10 D I 10 D 10 D K0037 A TEST 8	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO
0676 0677 0700 0701 0702 0703 0704 0705	1027 3010 0410 1012 1044 7042 7440 7402	CL TA DC AN TA CM SZ HL /AUTO INDE CL DC AN	A D K7737 A 10 D I 10 D 10 D K0037 A TEST 8 A K7677 A 10 V I 10	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR
0676 0677 0700 0701 0702 0703 0704 0705	1027 3010 0410 1012 1044 7042 7440 7402 7200 1026 3010	CL TA DC AN TA CM SZ HL /AUTO INDE CL TDC AN TA	A D K7737 6 10 D I 10 D 10 D K0037 A TEST 8 A K7677 A 10 F I 10 H 10	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED /DO AUTO INDEX
0676 0677 0700 0701 0702 0703 0704 0705 0706 0707 0710 0711	1027 3010 0410 1012 1044 7042 7440 7402 7200 1026 3010 0412 1010 1043	CL TA DC AN TA CM SZ HL /AUTO INDE CL TA DC AN TA	A D K7737 A 10 D I 10 D X0037 A TEST 8 A K7677 A 10 I 10 D X0077	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED
0676 0677 0700 0701 0702 0703 0704 0705 0707 0711 0711 07113 0714	1027 3010 0410 1012 1044 7042 7440 7402 7200 1026 3010 0412 1010 1043 7040	CL TA DC AN TA TA CM SZ HL /AUTO INDE CL TA DC AN TA	A D K7737 A 10 D I 10 D 10 D K0057 A TEST 8 A K7677 A 10 I 10 D K0077	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED /DO AUTO INDEX /AC SHOULD EQUAL 7777
0676 0677 0700 0701 0702 0703 0704 0705 0707 0710 0711 0712 0713	1027 3010 0410 1012 1044 7042 7440 7402 7200 1026 3010 0412 1010 1043	CL TA DC AN TA CM SZ HL /AUTO INDE CL TA DC AN TA	A D K7737 A 10 D I 10 D I 10 D K0057 A TEST 8 A 7677 A 10 I 10 I 10 D K0077 A	/DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED /DO AUTO INDEX

VAUTO INDEX TEST 9 CLA

0717	7200	CLA		
Ø72Ø	1025		K7577	/CONSTANT TO BE INDEXED
0721	3010	DCA	1 2	
Ø722	0410		Ī 10	/DO AUTO INDEX
Ø723	1010	TAP		
			KØ177	. /AC SHOULD EQUAL 7777
0724	1042	CMA	KOIII	, AC SHOULD EGUAL ////
Ø725	7040			110 OHOULD DE 7500
0726	7440	SZA		/AC SHOULD BE ZERO
Ø727	7402	HL!		/AUTO INDEX ERROR
				·
		/AUTO INDEX	TEST 10	
	7000	6 1 A		
0730	7200	CLA	v7777	/CONSTANT TO BE INDEXED
0731	1024		K7377	ACCIDATEM TO DE TIMPENED
0732	3010	DÇA		400 AUTO 1405V
Ø733	0410	ANU	1 10	/DO AUTO INDEX
0734	1010	TAU		
Ø735	1041	TAD	K0377	/AC SHOULD EQUAL 7777
0736	7040	CM&		
Ø737	7440	SZA		∕AC SHOULD BE ₹ERO
0740	7402	HLT		/AUTO INDEX ERROR
D/ 70	, , , ,	· -		
		/AUTO INDEX	TEST 11	
0741	7200	CLA		
_			K6777	/CONSTANT TO BE INDEXED
0742	1023			ACOMPLYMAL TO BE TABENED
0743	3010	DCA	10	(DO AUTO TAU)EY
0744	0410		Ī 10	/DO AUTO INDEX
Ø745	1010		10	44.0 AUG. 10 FAUAL 3373
0746	1040		KØ717	/AC SHOULD EQUAL 7777
0747	7040	CMA		
0750	7440	SZA		/AC SHOULD BE ZERO
0751	7402	HL!		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 12	
Ø752	7200	CLA		ARRIVE TO DE TUBELES
0753	1022		K5777	/CONSTANT TO BE INDEXED
0754	3010	DCA	10	
0755	2410		I 10	/DO AUTO INDEX
Ø756	7000	NOM		
Ø757	1010	T A -	10	
Ø76Ø	1037	TAD	K1777	/AC SHOULD EQUAL 1777
2761	7040	CMA	• 1	- · · · · · · · · · · · · · · · · · · ·
Ø762	7440	SZA		/AC SHOULD BE ₹ERO
07 6 3	7402	HLI		/AUTO INDEX ERROR
W/03	1702	P 66 /		A LOCATION PROPERTY OF A STATE OF

/AUTO INDEX TEST 15

0764	7200	CLM	
2765	1021	TAD K3777	CONSTANT TO BE INDEXED
Ø766	3018	DC+ 10	ADO ANTO INDEV
Ø767	0410	ANU I 18	/DO AUTO INDEX
0770	1010	TAD 10 Tau k3777	/AC SHOULD EQUAL 7777
0771	1021 7040	CMA	/ MO 0110 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
Ø772 Ø773	7448	SZA	/AC SHOULD BE ZERO
Ø774	7422	HL!	/AUTO INDEX ERROR
0775	7000	NOM	
0776	7006	NO#	
Ø 77 7	7000	NO.	

	1000	*1000		
		/AJTO INDEX	TEST 14	
1000	7200	CLA		
1001	1020	TAD	K7777	/CONSTANT TO BE INDEXED
1002	30 ₁ 0	DC	1 2	
1003	0410	AND	Ī 10	/DO AUTO INDEX
1004	1010	TAU	10	
1005	1020	TAD	K7777	/AC SHOULD EQUAL 7777
1006	7040	CMA		
1007	7410	SKP		
1010	0000	Ø		
1011	7440	SZ *		/AC SHOULD BE ZERO
1012	7402	HLT		/A _U TO INDEX ERROR
		/AUTO INDEX	TEST 15	·
1013	7200	CL*		
1014	1036	TAU	KØ	CONSTANT TO BE INDEXED
1015	3011	DCA	11	
1016	0411	AND	I 11	/DO AUTO INDEX
1017	1011	TAP	11	
1020	1035		K7776	/AC SHOULD EQUAL 7777
1021	7040	CMA		
1022	7440	SZA		/AC SHOULD BE ZERO
1023	7402	HLT		/AUTO INDEX ERROR
		/AJTO INDEX	TEST 16	
1024	7200	CLA		-
1025	1035	TAU	K7776	/CONSTANT TO BE INDEXED
1026	3011	DCA	11	
1027	0411		I 11	/DO AUTO INDEX
1030	1011	TAU	11	
1031	1036	TAD	K Z	/AC SHOULD EQUAL 7777
1032	7040	CM*		
1033	7440	SZA		/AC SHOULD BE ZERO
1034	7432	· HL!		/AUTO INDEX ERROR

		VAUTO INDEX	TEST 17	
1035	7200	CLA		ACCUSED TO BE INDEXED
1936	1034	TA	K7775	/CONSTANT TO BE INDEXED
1237	3011	DCA		ADD AUTO INDEV
1040	3411		I 11	/DO AUTO INDEX
1841	1011	TAN		/AC SHOULD EQUAL 7777
1342	1051		K0001	/AC SHOULD EGOAL ////
1043	7040	CMA		46 CHOW D DE 7500
1044	7440	SZA		/AC SHOULD BE ZERO
1245	7402	HLI		/AUTO INDEX ERROR
		/AUTO INDEA	TECT 18	
~	7200	CLA	1231 20	
1046	7200		K7773	CONSTANT TO BE INDEXED
1047	1033	DCA		
1050	3011		1 11	/DO AUTO INDEX
1051	1411	ĊĹĀ	: ++	
1052	7200	TAD	11	
1053	1011		K0003	/AC SHOULD EQUAL 7777
1054	1047	CMA	7000	
1055	7040 .	SZA		/AC SHOULD BE ZERO
1056	7 44 0 7 4 02	HLI		AUTO INDEX ERROR
1057	7402	ne.		
		/AUTO INDEX	TEST 19	
1060	7200	CLA		
1061	1032		K7767	CONSTANT TO BE INDEXED
1062	3011	DC=	11	
1063	0411	AND	1 11	/DO AUTO INDEX
1064	1011	TA-		
1065	1046	TAD	K0007	-
1066	7040	CM*		
1067	7440	S₹		/AC SHOULD BE ZERO
1070	7402	HLI		AUTO INDEX ERROR
		/AUTO INDEX	TEST 20	
1071	7200	CLA		
1072	1031		K7757	CONSTANT TO BE INDEXED
1073	3011	DC~	11	
1074	0411	AND	I 11	/DO AUTO INDEX
1075	1011	TAD	11	
1076	1045	TAD	K0017	/AC SHOULD EQUAL 7777
1277	7040	CMA		
1100	7440	SZA		/AC SHOULD BE FERD
1101	7402	HLT		/AUTO INDEX ERROR

		/AUTQ	INDEX	TEST 21	
1102	7200		CLA		
1103	1027			K1737	/CONSTANT TO BE INDEXED
1104	3211		DC#		AND MED THOSE
1105	0411			1 11	/DO AUTO INDEX
1106	1011		TAD	11 K0037	/AC SHOULD EQUAL 7777
1107	1044		TA	K D D 3 /	AMC SHOULD ENGAL 1///
1110	7040		CMA		/AC SHOULD BE ZERO
1111	7440		SZA HL1		/AUTO INDEX ERROR
1112	7402		ML.		ANDID THOSY SKKON
		OTLA/	INDEA	TEST 22	
1113	7200		CLA		
1114	1026		TA	K7677	CONSTANT TO BE INDEXED
1115	3011		DCA	11	
1116	0411			I 11	/DO AUTO INDEX
1117	1011		TA-		
1120	1043			KØØ17	/AC SHOULD EQUAL 7777
1121	7040		CMA		
1122	7440		SZA		/AC SHOULD BE ZERO
1123	7402		HLT		/AUTO IDEX ERROR
		/AUTO	INDEX	TEST 23	
1124	7200		CLA		
1125	1025		TAU	K7577	/CONSTANT TO BE INDEXED
1126	3011		DCA	11	
1127	0411		ANU	I 11	/DO AUTO INDEX
1130	1011		TAN		
1131	1042			K0177	/AC SHOULD EQUAL 7777
1132	7040		CMA		
1133	7440		SZA		/AC SHOULD BE ZERO
1134	7402		HLT		/AUTO INDEX ERROR
		OTUA\	INDEX	TEST 24	
1135	7200	-	CLA		
1136	1024		TAD	K7377	/CONSTANT TO BE INDEXED
1137	3011		DÇA	11	
1140	0411		AN-	I 11	/DO AUTO INDEX
1141	1011		TA		
1142	1041			KØ377	/AC SHOULD EQUAL 7777
1143	7040		CMA		_ •
1144	7440		SZA		/AC SHOULD BE ZERO
1145	7402		HLT		/AUTO INDEX ERROR

		/AUTO INDEX	TEST 25	
1146	7200	CLO		
1147	1023	TAP	K6777	/CONSTANT TO BE INDEXED
1150	3011	DC ··	11	
1151	0411	AND	Ī 11	/DO AUTO INDEX
1152	1011	TAN	11	
1153	1242	TAU	K0777	/AC SHOULD EQUAL 7777
1154	7048	CM	•	• • • • • • •
1155	7440	SZA		/AC SHOULD BE ≟ERO
1156	7402	HLI		AUTO INDEX ERROR
1170	1402			
		/AUTO INDEX	TEST 26	
1157	7200	CLA	-	
1160	1022		K5777	/CONSTANT TO BE INDEXED
1161	3011	DÇA	11	• • • • • • • • • • • • • • • • • • • •
1162	2411	152	i 11	/DO AUTO INDEX
1163	7000	NOP	•	
1164	1011	TA	11	
1165	1037		K1777	/AC SHOULD EQUAL 7777
1166	7040	CMA	N#777	
	7448	SZ*		/AC SHOULD BE ₹ERO
1167		HL!		AUTO INDEX ERROR
1170	7402	NOP		Andia titary riman
1171	7000	JMP	, + 4	
1172	5376	NOP	,	
1173	7000			
1174	7000	NOP		
1175	7000	NOP		
1176	7000	NOP		
1177	7000	NOP		

PAJSE

O

	.0.00	w 4 O (A)A		
	1200	*1200		
		XAGVI OTLA	TEST 27	
1200	7200	CL TA-	к3777	/CONSTANT TO BE INDEXED
1201 1202	1021 30 ₁₁	DÇA		
1203	0411	ANL	1 11	/DO AUTO INDEX
1204	1011	TAU	11 K3777	/AC SHOULD EQUAL 7777
1205 1206	1021 7040	CMA	K3///	AC SHOOLD EGONE ///
1200	7440	SZA		/AC SHOULD BE ZERO
1210	7402	нцт		AUTO INDEX ERROR
		/AUTO INDEX	TEST 28	
1211	7200	CLA	/ L J / L L	
1212	1020	TAU	k7717	CONSTANT TO BE INDEXED
1213	3011	00*		/DO AUTO INDEX
1214	0411	AND TAN	I 11 11	AND MOLD TUDEY
1215 1216	1011 1020		K7777	/AC SHOULD EQUAL 7777
1217	7048	CM*	, ,	_
1220	7440	SZA		/AC SHOULD BE ZERO
1221	7402	HLT		/AUTO INDEX ERROR
		/AJTO INDEX	TEST 29	
1222	7200	CLA		TO DE INDEVED
1223	1036	TA-	ΚØ 12	/CONSTANT TO BE INDEXED
1224 1225	3012 0412	AND		/DO AUTO INDEX
1226	1012	TAD	12	
1227	1035		K7776	/AC SHOULD EQUAL 7777
1230	7040	CMA		/AC SHOULD BE ZERO
1231 1232	7440 7402	SZA HL1		AUTO INDEX ERROR
1232	7402			
		/AUTO INDEX	TEST 30	
1233	7200	CLA	K1776	/CONSTANT TO BE INDEXED
1234 1235	1035 3012	DCA		
1236	0412	ANE	I 12	/DO AUTO INDEX
1237	1012	TAD	-	/AC SHOULD EQUAL 7777
1240	1036	TAU	k Ø	THE SHUDED EGONE ////
1241 1242	7042 7440	SZA		/AC SHOULD BE ZERO
1243	7422	HLT		AUTO INDEX ERHOR

/TEST 2 - TAPE 2

			TEST 31	
1244	7200	CLA		
1245	1034	TAD	K1775	/CONSTANT TO BE INDEXED
1246	3012	DCA	12	_
1247	3412	DCA	1 12	/DO AUTO INDEX
1250	1012	TAD	12	
1251	1051	TAP	K0001	/AC SHOULD EQUAL 7777
1252	7040	CM#		
1253	7440	SZA		∕AC SHOULD BE ZERO
1254	7402	HLT		/AUTO INDEX ERROR
		/AJTO INDEX	TEST 32	
1255	7200	CLA		
1256	1033		k77 73	/CONSTANT TO BE INDEXED
1257	3012	DCA	12	
1260	1412		1 12	/QO AUTO INDEX
1261	7200	CLA		
1262	1012	TAU	12	
1263	1047		K0003	/AC SHOULD EQUAL 7777
1264	7040	CMA		
1265	7440	SZA		/AC SHOULD BE ZERO
1266	7402	HL!		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 33	
1267	7200	CLA		
1270	1032	TÃU	K7767	CONSTANT TO BE INDEXED
1271	3012		12	
1272	0412	ANU	I 12	/DO AUTO INDEX
1273	1012	TAD	12	
1274	1046	TAU	K0007	/AC SHOULD EQUAL 7777
1275	7048	CMA		
1276	7440	SZA		/AC SHOULD BE ZERO
1277	7402	ዞ L1		/AUTO INDEX ERROR

		/AUTO INDE	X TEST 34	
1320	7200	CL		
1301	1031		D <7757	/CONSTANT TO BE INDEXED
1302	3012		A 12	ADD AMED INDEX
1303	0412		D I 12	/DO AUTO INDEX
1334	1012		U 12	/AC SHOULD EQUAL 7777
1305	1045 7040	1 A C M	₩ KØØ17	/AC SHOULD EQUAL ////
1306	7440	S Z		/AC SHOULD BE ZERO
1307 1312	7402	9 E		AUTO INDEX ERROR
1015	1402	11	,	THE STATE OF THE S
		/AUTO INDE	A TEST 35	
1311	7200	CL	**	
1312	1027		U K7737	/CONSTANT TO BE INDEXED
1313	3012		A 12	
1314	0412		L I 12	/DO AUTO INDEX
1315	1012		12	
1316	1044	TA		/AC SHOULD EQUAL 7777
1317	7040	CM		DE 7600
1320	7440	S₹		/AC SHOULD BE ₹ERO
1321	7402	HL	1	/AUTO INDEX ERROR
		/AJFO INDE	X TEST 36	
1322	7200	CL		
1323	1026		₩ K7677	/CONSTANT TO BE INDEXED
1324	3012	DC	A 12	
1325	0412	AN		/DO AUTO INDEX
1326	1012		U 12	
1327	1043		¥ KØØ77	/AC SHOULD EQUAL 7777
1330	7040	CM		4.0 0000 D 05 7000
1331	7440	S≠		/AC SHOULD BE ZERO
1332	7402	HL		/AUTO INDEX ERROR
		ZAUTO INDE	A TEST 37	
1333	7200	CL		
1334	1025	TA	U K7577	/CONSTANT TO BE INDEXED
1335	3012	DC	A 12	
1336	0412		U I 12	/DO AUTO INDEX
1337	1312		12	
1342	1042		₽ KØ1/7	/AC SHOULD EQUAL 7777
1341	7040	CM		
1342	7440	S₹		/AC SHOULD BE ZERO
1343	7402	HL	i	/AUTO INDEX ERROR

		/AUTO INDEX	TEST 38	
1344	7200	CLA	-	
1345	1024		K7377	/CONSTANT TO BE INDEXED
1346	3012		12	
1347	0412	AND	1 12	/DO AUTO INDEX
1350	1012	TAU		, po
		TA₽		/AC SHOULD EQUAL 7777
1351	1041	CMA	N D 3 / /	AC SHOULD ENGAL ATT
1352	7040			ALC CHAIR D. DE ZEDO
1353	7440	SZA		VAC SHOULD BE ZERO
1354	7402	HL		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 39	
1355	7200	CLA		
1356	1023	TÂU	K6777	/CONSTANT TO BE INDEXED
1357	3012	DC-	12	•
1360	0412		I 12	/DO AUTO INDEX
1361	1012	TA	12	
1362	1040	TAD	K0777	/AC SHOULD EQUAL 7777
1363	7040	CMA	N	, No Shoggs adams
1364	7440	SZA		/AC SHOULD BE ZERO
_	7402	HLT		/AUTO INDEX ERROR
1365	1702	n p i		AND INDEX ENGE
		/AUTO INDEX	TEST 40	
₁ 366	7200	CL		
1 367	1022	TAD	K5777	/CONSTANT TO BE INDEXED
1370	3012	DÇA	12	
1371	2412	Is≠	Ī 12	/DO AUTO INDEX
1372	7000	NÕP		
1373	1012	TAU	12	
1374	1037	TAD	K1777	/AC SHOULD EQUAL 7777
1375	7040	CMA		
1376	7440	SZA		/AC SHOULD BE ZERO
1377	7402	HL!		/AUTO INDEX ERROR
10//	, " U C	(1 ,		The same arrest and arrest and arrest

1420	*1400 /AUTO INDEX TEST 41	
1400 7200	CL 4	TO DESCRIPTION OF THREE DESCRIPTIONS
1401 1021	TAD K3777	CONSTANT TO BE INDEXED
1402 3012	DC# 12 And I 12	/DO AUTO INDEX
1403 0412 1404 1012	TAU 12	
1404 1012	TAD K3777	/AC SHOULD EQUAL 7777
1426 7040	CMA	CHOULD BE 3590
1407 7440	SZA HLT	/AC SHOULD BE ZERO /AUTO INDEX ERROR
1410 7402	7 . .	YAUTO THEEK PHOTO
	VAUTO INDEX TEST 42	
1411 7200	CLA	CONSTANT TO BE INDEXED
1412 1020	TAN K7777 DCA 12	ACOMPLANT TO BE THREETED
1413 3012	AND I 12	/DO AUTO INDEX
1414 0412 1415 1012	TAD 12	
1416 1020	TAN K7777	/AC SHOULD EQUAL 7777
1417 7040	CM≛	ALC CHOM D. DE ZEDO
1420 7440	SŽA	∕AC SHOULD BE ₹ERO ∕AUTO INDEX ERROR
1421 7402	HĻ [↑]	AND THOUX THUON
	/AUTO INDEX TEST 43	
1422 7200	CLA	/CONSTANT TO BE INDEXED
1423 1036	TAD KU DCA 13	ACOMPLANT TO BE IMPEXED
1424 3013	ANU I 13	/DO AUTO INDEX
1425 Ø413 1426 1013	TAU 13	
1427 1035	TA- K7776	/AC SHOULD EQUAL 7777
1430 7040	CMA	/AC SHOULD BE ZERO
1431 7440	SZ- HL+	/AC SHOULD BE ZERO /AUTO INDEX ERROR
1432 7402	Ph. 1	y acto intervention
	/AUTO INDEA TEST 44	
1433 7200	CLA	CONCIANT TO BE INDEVED
1434 1035	TA- K7776 DCA 13	CONSTANT TO BE INDEXED
1435 3013 1436 0413	ANN I 13	/DO AUTO INDEX
1436 0413 1437 1013	TAU 13	
1440 1036	TAD KU	/AC SHOULD EQUAL 7777
1441 7040	CMA	/AC SHOULD BE ZERO
1442 7440	SZA HLT	/AUTO INDEX ERROR
1443 7402	761	YAUTU INTERNIOR
	/AUTO INDEX TEST 45	
1444 7200	CLA	CONSTANT TO BE INDEXED
1445 1034	TAU K7775 DCA 13	ACCINDING TO BE THEFTED
1446 3013 1447 3413	DCA 13	/DO AUTO INDEX
1447 3413 1450 1313	TAU 13	
1451 1351	TAU K0001	/AC SHOULD EQUAL 7777
1452 7040	CM ^A	AC SHOULD DE ZERO
1453 7440	S ± *	/AC SHOULD BE ZERO

Ę

		/AUTO INDEX TEST 46	
1455	7200	CL#	CONSTANT TO BE INDEXED
1456	1033	TAU K7773	ACOMPLANT TO BE TABEYED
1457	3013	DC# 13	/DO AUTO INDEX
1460	1413	TAD I 13	AND MOTO THREE
1461	7200	CLA TA- 13	
1462	1013	TAD K0003	/AC SHOULD EQUAL 7777
1463	1347	CMA	
1464	7040 7440	S £ 4	/AC SHOULD BE ZERO
1465 1466	7402	HL!	/AUTO INDEX ERROR
1400	1702		
		/AJTO INDEA TEST 47	
1467	7200	CLA	CONSTANT TO BE INDEXED
1470	1032	TA- K7767	ACOMPIANT TO BE TABLETO
1471	3013	DCA 13	ZDO AUTO INDEX
1472	Ø413	ANU I 13	ADO MOTO THREE
1473	1013	TAD 13	/AC SHOULD EQUAL 7777
1474	1246	TAD KØØØ7	AC SHOOLD EGONE ////
1475	7040	CMA	/AC SHOULD BE ZERO
1476	7440	SZ~ HL1	AUTO INDEX ERROR
1477	7402	76'	, Ag , G . Ma = A M. G
	-	/AUTO INDEX TEST 48	
1500	7200	CL*	/CONSTANT TO BE INDEXED
1501	1031	TAU K77>7	ACOMPTANT TO BE INDEXED
1502	3013	DCA 13	
1503			ADD AUTO TAUDEY
1003	0413	AND I 13	/DO AUTO INDEX
1504	1013	TA 13	, - , - , - , - , - , - , - , - , - , -
1504 1505	1013 1045	TA 13 TAD K0017	/DO AUTO INDEX /AC SHOULD EQUAL 7777
1504 1505 1506	1013 1045 7040	TA 13 TAD K0017 CMA	/AC SHOULD EQUAL 7777
1504 1505 1506 1507	1013 1045 7040 7440	TA 13 TAD K0017 CMA SZA	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO
1504 1505 1506	1013 1045 7040	TA 13 TAD K0017 CMA	/AC SHOULD EQUAL 7777
1504 1505 1506 1507	1013 1045 7040 7440	TA 13 TAD K0017 CMA SZA HL! /AJTO INDEA TEST 49	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO
1504 1505 1506 1507	1013 1045 7040 7440	TA 13 TAD K0017 CMA SZA HL! /AJTO INDEA TEST 49 CLA	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR
1504 1505 1506 1507 1510	1013 1045 7040 7440 7402	TA 13 TAD K0017 CMA SZA HL! /AUTO INDEA TEST 49 CLA TAD K/737	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO
1504 1505 1506 1507 1510	1013 1045 7040 7440 7402	TA 13 TAD K0017 CMA SZA HL! /AUTO INDEA TEST 49 CLA TAD K/737 DCA 13	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED
1504 1505 1506 1507 1510 1511 1512 1513 1514	1013 1045 7040 7440 7402 7200 1027	TA 13 TAD K0017 CMA SZA HL! /AUTO INDEA TEST 49 CLA TAD K/737 DCA 13 ANU I 13	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR
1504 1505 1506 1507 1510 1511 1512 1513	1013 1045 7040 7440 7402 7200 1027 3013 0413 1013	TA 13 TAD K0017 CMA SZA HL! /AUTO INDEA TEST 49 CLA TAD K/737 DCA 13 ANW I 13 TAW 15	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED /DO AUTO INDEX
1504 1505 1506 1507 1510 1511 1512 1513 1514	1013 1045 7040 7440 7402 7200 1027 3013 0413 1013	TA 13 TAD K0017 CMA SZA HL! /AUTO INDEA TEST 49 CLA TAD K/737 DCA 13 ANU I 13 TAU 13 TAU K0037	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED
1504 1505 1506 1507 1510 1511 1512 1513 1514 1515 1516 1517	1013 1045 7040 7440 7402 7200 1027 3013 0413 1013 1044 7040	TA 13 TAD K0017 CMA SZA HLI /AUTO INDEA TEST 49 CLA TAD K/737 DCA 13 ANU I 13 TAU 13 TAU K0037 CMA	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED /DO AUTO INDEX /AC SHOULD EQUAL 7777
1504 150067 1512 15113 151167 1512 1512 1512 1512 1512	1013 1045 7040 7440 7402 7200 1027 3013 0413 1013 1044 7040 7440	TA 15 TAD K0017 CMA SZA HL /AUTO INDEA TEST 49 CLA TAD K/737 DCA 13 ANU I 13 TAU 15 TAU K0037 CMA SZ#	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED /DO AUTO INDEX /AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO
1504 1505 1506 1507 1510 1511 1512 1513 1514 1515 1516 1517	1013 1045 7040 7440 7402 7200 1027 3013 0413 1013 1044 7040	TA 13 TAD K0017 CMA SZA HLI /AUTO INDEA TEST 49 CLA TAD K/737 DCA 13 ANU I 13 TAU 13 TAU K0037 CMA	/AC SHOULD EQUAL 7777 /AC SHOULD BE ZERO /AUTO INDEX ERROR /CONSTANT TO BE INDEXED /DO AUTO INDEX /AC SHOULD EQUAL 7777

		/AUTO INDE	X TEST 50	
1522	7200	CL	A	
1523	1026	TA	D K7677	/CONSTANT TO BE INDEXED
1524	3013	DC	13	
1525	0413	AN	D 1 13	/DO AUTO INDEX
1526	1013	TA		
1527	1043		J K0017	/AC SHOULD EQUAL 7777
1530	7040	CM		
1531	7440	S 2		/AC SHOULD BE ZERO
	7402	HL		AUTO INDEX ERROR
1732	1702	m .		Audio iliany number
1		JAJTO INDE	X TEST 51	
	7200	, , , , , , , , , , , , , , , , , , , ,	CLA	
1534	1025	TA	X7577	CONSTANT TO BE INDEXED
1535	3013		A 13	
1536	Ø413	AN		/DO AUTO INDEX
1537	1013		13	v v v v v v v v v v v v v v v v v v v
		TA		/AC SHOULD EQUAL 7777
1540	1042	ĊM	9	AND SHOOLD EGGAE ****
1541	7040	S Z		/AC SHOULD BE ZERO
1542	7440	HL		AUTO INDEX ERROR
1543	7402	n.	'	PROTO INDEX ERROR
		/AJTO INDE	X TEST 52	
1544	7200	CL		
1545	1024		¥ K7377	/CONSTANT TO BE INDEXED
1546	3013		13	
1547	Ø413	AN	√ Î 13	/DO AUTO INDEX
			J 13	- go mg to time:
1550	1013	! A	L K0377	/AC SHOULD EQUAL 7777
1551	1041	ĆM		AC SHOPED EBONE TOTAL
1552	7040	SZ.		/AC SHOULD BE ZERO
1553	7440	HL SE		AUTO INDEX ERROR
1554	7402	75	'	ANDIO INDEX CHRON
		/AJTO INDE	X TEST 53	
1555	7200	CL		
1556	1023		3 K6777	/CONSTANT TO BE INDEXED
1557	3013		4 13	
			1 13	/DO AUTO INDEX
1560	0413		J 13	· WA MAIO PUREV
1561	1013	TA		/AC SHOULD EQUAL 7777
1562	1042			AND CHOOSE MARKET !!!
1563	7240			∕AC SHOULD BE ŽERO
1564	7440			AUTO INDEX ERROR
1565	7402	HL	ı	AMOID THUEN EMMUN

		/AJTO INDEX	TEST 54	
1566	7202	CL#		
1567	1022	TAU	ĸ	/CONSTANT TO BE INDEXED
1570	3213	DC A	13	
1571	2413	IS≠	: 13	/DO AUTO INJEX
1572	7222	NOF		
157 3	1013	TAW	13	
1574	1037	TA→	K1777	/AC SHOULD EQUAL 7777
1575	7042	CM+		
1576	7440	S <i>₹~</i>		/AC SHOULD BE ∠ERO
1577	7402	HL!		/AUTO INDEX ERROR

	1600	*1600		
		/AUTO INDEX	TEST 55	
1600	7200	CLA		
1601	1021		∢3777	/CONSTANT TO BE INDEXED
1602	3013	DCA	-	
1603	0413	ANU		/DO AUTO INDEX
1604	1013	TA-	13	4
1605	1021	TAD	∢ 3777	/AC SHOULD EQUAL 7777
1606	7040	CM*		
1627	7440	SZA		/AC SHOULD BE ZERO
1610	7402	HL 1		/A _U TO INDEX ERROR
		/AUTO INDEX	TEST 56	
1611	7200	CLA		
1612	1020		K7777	/CONSTANT TO BE INDEXED
1613	3013	DC*	13	
1614	0413	·ANU		/DO AUTO INDEX
1615	1013	TAD		
1616	1020	TAD	K7777	/AC SHOULD EQUAL 7777
1617	7040	Cm*		
1620	7440	SZA		/AC SHOULD BE ZERO
1621	7402	HLT		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 57	
1622	7200	CLA		
1623	1036	TAP	KØ	CONSTANT TO BE INDEXED
1624	3014	DC#	14	
1625	0414	AND		/DO AUTO INDEX
1626	1014	TA	14	
1627	1035		K7776	/AC SHOULD EQUAL 7777
1630	7040	CM "		
1631	7440	SZA		/AC SHOULD BE ZERO
1632	7402	HLI		/AUTO INDEX ERROR

		/AJTO IN	DEX	TEST 58	
1633	7200		CL"		
1634	1235			≺7776	CONSTANT TO BE INDEXED
1635	3214		DCA	14	
1636	0414			I 14	/DO AUTO INDEX
1637	1214		TA-		
1642	1036		TAD	ΚŊ	/AC SHOULD EQUAL 7777
1641	7040		ÇM		
1642	7440		SZA		/AC SHOULD BE ZERO
1643	7402		HLT		/AUTO INDEX ERROR
		/AUTO IN		TEST 59	
1544	7202		CLA		
1645	1034			K7775	CONSTANT TO BE INDEXED
1646	3014		DC#		
1647	3414			I 14	/DO AUTO INDEX
1650	1014		TAU	-	4.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5
1651	1051			K0001	/AC SHOULD EQUAL 1777
1652	7040		CMA		
1653	7440.		SZA		VAC SHOULD BE ZERO
1654	7402		HLT		/AUTO INDEX ERROR
		/AJTO IN	-	TEST 60	
1655	7200		CL#		
1656	1033		•		CONSTANT TO BE INDEXED
1657	3214		DÇ4		(00 LUES 11/25V
1662	1414			I 14	/DO AUTO INDEX
1661	7200		CL A		
1662	1014		TA		//C CHOULD COUNT 7777
_	1047			K0003	/AC SHOULD EQUAL 7777
1664	7040		CMA		446 6U6ULD DE 7500
1665	7440		SZA		/AC SHOULD BE ZERO /AUTO INDEX ERROR
1666	7402		HLI		AND INDEX FRANK
		/AJTO IN		TEST 61	
1667	7200		CLA		
1677	1032			K7767	/CONSTANT TO BE INDEXED
1671	3014		DC#	-	400 AUTO TAUDEN
1672	0414			1 14	/DO AUTO INDEX
1673	1014		TAU		AND CHOILD COMMITTEE
1674	1046			K 2027	/AC SHOULD EQUAL 7777
1575	7040		CMA		AC CHOULD BE 7550
1676	7440		SZA		/AC SHOULD BE ZERO
1677	7422		HLT		/AUTO INDEX ERROR

HL!

1743 7422

/AUTO INUEX ERROR

_		/AJTO INDEX		
1744	7200	CLA		ARRHETANT TO BE INDEVED
1745	1024	T A D	K7377 14	CONSTANT TO BE INDEXED
1746 1747	3014 0414	ANU		/DO AUTO INDEX
1750	1014	TA»		100 WO O THREE
1751	1014	•	K0377	/AC SHOULD EQUAL 7777
1752	7040	CMA		
1753	7442	SZA		/AC SHOULD BE ZERO
1754	7402	H_ I		VAUTO INDEX ERROR
		/AJTO INDEX	TEST 67	
1755	7200	CLA		
1756	1023		K6777	/CONSTANT TO BE INDEXED
1757	3014	DCA	-	
1760	0414	ANS		/DO AUTO INDEX
1761	1014	TAU		4.0.00000000000000000000000000000000000
1762	1042	TAL	K0777	/AC SHOULD EQUAL 7777
1763	7242	CM.~		250
1764	7440	SZA		/AC SHOULD BE ZERO
1765	7402	HLI		/AUTO INDEX ERROR
	_	/AJTO INDL	X TEST 68	
1766	7200	CL#		
1767	1022	TAD	K5777	/CONSTANT TO BE INDEXED
1770	3214	DC ^A		
1771	2414	IS≢	I 14	/DO AUTO INDEX
1772	7000	NO		-
1773	1014	TAU	-	
1774	1037		K1777	/AC SHOULD EQUAL 7777
1775	7040	CMA		ALC CHANNE DE TERM
1776	7440	SZA		/AC SHOULD BE ZERO
177 7	7402	HL1		/AUTO INDEX ERROR

	2006	*2200 /AJTO IND	ne X	TEST A9	
2000	7200	ם וויים וכורי	LA	1231 01	
2000	1021			K3717	CONSTANT TO BE INDEXED
2002	3014		CA		,
2002	0414			ī 14	/DO AUTO INDEX
2003	1014		AD		, , , , , , , , , , , , , , , , , , , ,
_				± · ⊀ 3 7 7 7	/AC SHOULD EQUAL 7777
2005 2006	1021 7040		MA	(0),,,	THE CHOOLS GOVE TOTAL
	7410		K		
2007		0			
2010	0000		ZΑ		/AC SHOULD BE ZERO
2011	7440				/AUTO INDEX ERROR
2012	7402	7	L		AND THEY ENGH
		/AJTO IND	Få	TEST 70	
0.04.7	7200		L #	1431 /-	
2013	1020			K7777	/CONSTANT TO BE INDEXED
2014			C =		YOURSTAND TO BE INSERED
2015	3014			I 14	/DO AUTO INDEX
2016	0414		AD		,00 M010 IMPEN
2017	1014			17 K7777	/AC SHOULD EQUAL 7777
2020	1020			K////	AC SHOOFD EGGME
2021	7040		MA		/AC SHOULD BE ZERO
2022	7442		ZA		•
2023	7402	H	LT		/AUTO INDEX ERROR
		ZAUTO IND	EX	TEST 71	
2024	7200	C	LA		
2025	1036		AL	KØ	/CONSTANT TO BE INDEXED
2026	3015		CA		
2027	0415	-		I 15	/DO AUTO INDEX
2030	1015		AD		0 414 ==
2030	1035			k7776	/AC SHOULD EQUAL 7777
2032	7040		MA	1,	
	7440		ž		/AC SHOULD BE ZERO
2033 2034	7402	_	ILT		/AUTO INDEX ERROR
2034	/ 702		1 (20-1		
		/AJTO IND	£Χ	TEST 72	
2035	7200		LA		
2036	1035	7	AL	K7776	/CONSTANT TO BE INDEXED
2037	3015	D	CA	15	
2040	0415	A	NU	1 12	/DO AUTO INDEX
2041	1015	T	AU	15	
2042	1036		Δ U		/AC SHOULD EQUAL 7777
2043	7240	С	MA	•	· · · · · · · · · · · · · · · · · · ·
2244	7440		ZA		/AC SHOULD BE ZERO
2045	7402		16		/AUTO INDEX ERROR
2077			_		
		JAJTO IND	E A	TEST 75	
2046	7200		LA		
2047	1234	T	AU	K/775	CONSTANT TO BE INDEXED
2253	3015) C	15	
2201	3415	D	CA	I 15	/DO AUTO INDEX
2352	1215	T	4	15	- 11
2253	1051	*	UA	K0001	/AC SHOULD EQUAL 7777
	*				

1/22/6 5:43,47 PAGE 32-1

2054 7040 2055 7440 2056 7402

SZ /AC SHOULD BE ZEPO HLT /AUTO INDEX ERROR

CMA

.

		I OTUAL	NDEX	TEST 74	
2057	7200		CLA		
2060	1033			k 1773	/CONSTANT TO BE INDEXED
			•	15	
2061	3015			_	ADD AUTO INDEV
2062	1415			Į 15	/DO AUTO INDEX
2063	7200		CLA		
2064	1015		TAU		
2065	1047			K0003	/AC SHOULD EQUAL 7777
2066	7040		CMA		
2067	7440		SZA		/AC SHOULD BE ZERO
2070	7402		HLI		/AUTO INDEX ERROR
2010	7702				,
		I OTLA\	NDEY	TI CT 75	
	7200	/AUTO I		1431 /2	
2071	7200		CL.		/CONSTANT TO BE INDEXED
2072	1032			K7767	ACOMPLANT TO BE TANEYED
2073	3015		DÇA		
2074	0415			1 15	/DO AUTO INDEX
2075	1015		TA-	15	
2076	1046		TAD	K0007	/AC SHOULD EQUAL 7777
2077	7040		CM~		
2100	7440		SZA		/AC SHOULD BE ZERO
					/AUTO INDEX ERROR
2101	7402		HLT		NAPLO THREY SKURU
		4	MACV	TC07 76	
		I OTLA\		TESI 10	
2102	7200		CLA		TOURS TO OF TURENTS
2103	1031		,	K7757	/CONSTANT TO BE INDEXED
2104	3015	*		15	
2105	0415		AN	I 15	/DO AUTO INDEX
2106	1015		TAL	15	
2107	1045		TAN	K0017	/AC SHOULD EQUAL 7777
	7242		CM*	,	
2110	7440		SZA		/AC SHOULD BE ZERO
2111			HLT		/AUTO INDEX ERROR
2112	7402		M.C.		NAGIO THOEX ERVOR
		I DILA\		TEST 77	
2113	7200		CL"	_	
2114	1027				/CONSTANT TO BE INDEXED
2115	3015		DCA	15	
2116	0415		AND	Ī 15	/DO AUTO INDEX .
2117	1015		TAU		•
2122	1044			K0037	/AC SHOULD EQUAL 7777
			CMA		हात्वच कराच्याभू क्रम्याच्याक प्राप्त कर्मा क्रम्याच्या प्राप्त कर्मा क्रम्याच्या प्राप्त कर्मा क्रम्याच्या प्र
2121	7040				/AC SHOULD BE ZERO
2122	7440		SZA		
2123	7402		HLI		/AUTO INDEX ERROR

NO '

NO "

NUF

NOP

NOF

JMF ,+4 NOF

2171 7000 2172 5376

2173 7002

2174 7000

2175 7002

2176 7002 2177 7000

	2200	*2200			
		/AUTO		TEST 82	
2200	720°		CLA		
2201	1022			K5777	/CONSTANT TO BE INDEXED
2202	3015			15	
2203	2415			I 15	/DO AUTO INDEX
2204	7000		NOF		
2205	1015		TAP		
2206	1037			K1777	/AC SHOULD EQUAL 7777
2207	7040		CMA		
2210	7440		SZA		/AC SHOULD BE ZERO
2211	7402		HLI		/AUTO INDEX ERROR
		/AUT0 1	INDEX	TEST 83	
2212	7200		CLA		
2213	1021		TAU	K3777	/CONSTANT TO BE INDEXED
2214	3015		DCA		_
2215	0415		AN-	I 15	/DO AUTO INDEX
2216	1015		TAU		
2217	1021			K3777	/AC SHOULD EQUAL 7777
2220	7040		CM#		
2221	7440		SZA		/AC SHOULD BE ZERO
2222	7402		HLI		/AUTO INDEX ERROR
		ZAUTO 1	INDEA	TEST 84	
2223	7200	7 4 3 1 0 3	CL -	140, 6	
2224	1020			K7777	/CONSTANT TO BE INDEXED
2225	3015		DC-		
2225	0415			I 15	/DO AUTO INDEX
2227	1015		TAU		
2232	1020			K1777	/AC SHOULD EQUAL 7777
2231	7040		CMA		
2232	7440		SZA		/AC SHOULD BE ZERO
2233	7402		HL		AUTO INDEX ERROR
2233	1406		F1899		
		/AJTO 1		TEST 85	
2234	7200		CLA	a	ACONC.AND TO DE INDEVED
2235	1036		TAU		CONSTANT TO BE INDEXED
2236	3216		DC*	-	ADD AHTS TORY
2237	0416			I 16	- /DO AUTO INDEX
2240	1016			16	ALC CHOULD COURT 7777
2241	1035			K7776	/AC SHOULD EQUAL 7777
2242	7040		CM-		AC CHOULD DE TEDO
2243	7440		SZA		/AC SHOULD BE ZERO
2244	7402		HLT		/AUTO INDEX ERROR

		/AUTO I	NDEX	TEST 86	
2245	7202		CL"	ĸ7776	/CONSTANT TO BE INDEXED
2246 2247	1035 3016		DC "	16	
225∂ 2251	2416 1416		ANU	I 16	/OO AUTO INDEX
2252	1236		TAU		/AC SHOULD EQUAL 7777
2253 2254	7040 7440		CMA SZ4		/AC SHOULD BE ZERO
2255	7402		HL!		AUTO INDEX ERROR
		/AUTO I	NDEA	TEST 87	
2256	7200	, <u>.</u>	CLA	k7775	CONSTANT TO BE INDEXED
2257 2260	1034 30 ₁ 6		DÇA		
2261	3416		DCA TAU	I 16	/DO AUTO INDEX
2262 2263	1016 1051		TAD	K0001	/AC SHOULD EQUAL 7777
2264	7046		CM" SZA		/AC SHOULD BE ZERO
2265 2266	7440 7402		HLT		AUTO INDEX ERROR
		I OTLA\	NDFX	TEST 88	
	7202	/ # J 1 0 1 1	CL		CONCTANT TO BE INDEVED
227Ø 227 ₁	1033 30 ₁ 6			k7773	/CONSTANT TO BE INDEXED
2272	1416		TAD	Ī 16	/DO AUTO INDEX
2273 2274	7202 1016		CLA	16	
2275	1047		TAU CM ^A	K0003	/AC SHOULD EQUAL 7777
2276 2277	7040 7440		SZA		/AC SHOULD BE ZERO
2300	7402		HL!		/AUTO INDEX ERROR
		I OTLA/		TEST 89	
2301 2302	7200 1032		CLA	K7767	CONSTANT TO BE INDEXED
2302	3016		DCA	16	100 AUEO INOEV
2304 2305	2416 1310		TAD	I 16	/DO AUTO INDEX
2326	1046		TAU	K2007	/AC SHOULD EQUAL 7777
2307 2310	7042 7442		CMA SZA		/AC SHOULD BE ZERO /AUTO INDEX ERROR
2311	7402		HL		
0716	7001	/AUTO 1	NDE^	TEST 90	
2312 2313	7202 1331			×7757	/CONSTANT TO BE INDEXED
2314	3010		DCA	16 I 10	/DO AUTO INDEX
2315 2316	0416 1010		TA	16	
2317	1345		TAD	x0017	/AC SHOULD EQUAL 7777
2320	7042		CHA		

1.	12	2	1	68	1:	· :	4	3	. õ	3	
----	----	---	---	----	----	-----	---	---	-----	---	--

PAUL U. #1

		- 0		10 000 10 0E 7500
2321	7440	SZA		/AC SHOULD BE ZERO
2322	7402	HLT		/AUTO INDEX ERROR
		/AJTO INDEX	TEST 91	
2323	7200	CLA		
2324	1027	TAU	K7737	/CONSTANT TO BE INDEXED
2325	3016	DCA	16	
2326	Ø416	ANU	I 16	/DO AUTO INDEX
2327	1016	TAU	16	
2330	1044	TAU	K0037	/AC SHOULD EQUAL 7777
2331	7040	CMA		
2332	7440	SZA		/AC SHOULD BE ZERO
2333	7402	HL I		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 92	
2334	7200	CL*		
2335	1026		к767 7	/CONSTANT TO BE INDEXED
2336	3016	DCA	· -	
2337	Ø416		I 16	/DO AUTO INDEX
2340	1016	TAU		
2341	1010	TAU	K0077	/AC SHOULD EQUAL 7777
2342	7040	CMA	K-D.	
2343	7440	SZA		/AC SHOULD BE ZERO
2344	7402	HL!		AUTO INDEX ERROR
2344	1702			THE TOTAL STATE OF THE STATE OF
		/AUTO INDEX	TEST 95	
2345	7200	CLA		
2346	1025	TAU	K7577	CONSTANT TO BE INDEXED
2347	3016	DC	16	
2350	0416	ANU	I 16	/DO AUTO INDEX
2351	1016	TAD	16	
2352	1042	TAD	KØ177	/AC SHOULD EQUAL 7777
2353	7040	CMA		
2354	7440	SZA		/AC SHOULD BE ZERO
2355	7402	HL		/AUTO INDEX ERROR

		/AUTO INDEX	TEST 94	
2356 2357	7200 1024	CLA	k7377	/CONSTANT TO BE INDEXED
2360 2361	3016 0416	DCM	1 16	/DO AUTO ĮNJEX
2362 2363	1016 1041	TAD TAU CMA	10 KØ377	/AC SHOULD EQUAL 1777
2364 2365 2366	7040 7440 7402	S.₹ HLT		/AC SHOULD BE ZERO /AUTO INDEX ERROR
		/AJTO INDEX	TEST 95	
2367 2370	7200 1023	·	K6777	/CONSTANT TO BE INDEXED
2371 2372	3016 0416	DÇA AN	I 16	/DO AUTO INDEX
2373 2374	1016 1040	TAD TAP	16 K0777	/AC SHOULD EQUAL 7777
2375 2376	7040 7440	CM# S₹* HL!		/AC SHOULD BE ZERO /AUTO INDEX ERROR
2377	7402	Γ .		

*

/TEST	2	5	TAPE	3

		, 120,		
	2400	* 2 4 V K		
		/AJTO INDEX	TEST 96	
2400 2401 2402	7200 1022 3016	CLA TAE DC#	қ5777 16	CONSTANT TO BE INDEXED
2403 2404	2416 7000	ISZ NOP TAP	1 16	∕QO AUTO INDEX
2405 2406 2407	1016 1037 7040		K1777	/AC SHOULU EQUAL 7777
2410	7440 7402	S ± A HL T		/AC SHOULD BE ZERO /AUTO INDEX ERROR
			TEST 97	
2412 2413	7200 1021	CLA TAU	K 57/7	/CONSTANT TO BE INDEXED
2414 2415	3016 0416	DC ANU TA	I 16	/DO AUTO INDEX
2416 2417 2420	1016 1021 7040		K3777	/AC SHOULD EQUAL 7777
2421 2422	7440 7402	SZA HL I		/AC SHOULD BE ZERO /AUTO INDEX ERROR

		VAJTO INDEX	TEST 98	
2423	7200	CL*		
2424	1020	TAU	K7777	/CONSTANT TO BE INDEXED
2425	3016	DCA	1.6	
2426	Ø416		I 16	/DO AUTO INDEX
2427	1016	TA	16	
2430	1020	· · · · · · · · · · · · · · · · · · ·	K7777	/AC SHOULD EQUAL 7777
	7040	CMA	7////	, no onlogge adong try
2431	7448	SZA		/AC SHOULD BE ZERO
2432		HL!		ZAUTO INDEX ERROR
2433	7402	n.		ANDIO IMPEN CHUON
		/AUTO INDEA	TEST 99	
2434	7200	CL#	1-0.	
2435	1036	TAD	K Ø	/CONSTANT TO BE INDEXED
	3017	DCA		\$ DOMO FAIR TO DO \$ 1 PONTS
2436	0417		I 17	/DO AUTO INDEX
2437		TAU		780 HOTO 1HDEK
2440	1017		K7776	/AC SHOULD EQUAL 7777
2441	1035	CM-	K7770	AND SHOOFD EGANE
2442	7040	SZA		/AC SHOULD BE ₹ERQ
2443	7442	_		AUTO INDEX ERROR
2444	7402	HLT		NAUTO THOEX ERROR
		/AUTO INDEX	TEST 100	
2445	7200	CLA	-	
2446	1035	TA	k7776	/CONSTANT TO BE INDEXED
2447	3017	DC*		
2450	0417		Ī 17	/DO AUTO INDEX
2451	1017	TA	-	• • • • • • • • • • • • • • • • • • • •
2452	1036	TAD		/AC SHOULD EQUAL 7777
2453	7040	CMA	.,,	
2453	7440	SZA		/AC SHOULD BE ZERO
2454	7400	HLI		AUTO INDEX ERROR
2400	7402	(1 L		
		/AUTO INDEX	TEST 101	
2456	7200	CL"		
2457	1034	TAU	K7775	/CONSTANT TO BE INDEXED
2460	3017	DC≃	17	
2461	3417	DCA	Ĩ 17	/DO AUTO INDEX
2462	1017	TAG	17	
2463	1051	TAD		/AC SHOULD EQUAL 7777
2464	7042	CMA		•
2465	7440	SZA		/AC SHOULD BE ZERO
2466	7422	HL		/AUTO INDEX ERROR
2400	1766	75		र प्रमाण के प्राचालकार का जा पर का प्र

		/AUTO INDEX	TEST 162	
2467	7200	CLA		
2470	1033	T A	K7713	ACONSTANT TO BE INDEXED
2471	3017	DCA	17	
2472	1417	TAU	1 17	XADNI OTUA OCY
2473	7200	CLA		
2474	1017	TAU	17	
2475	1047	TAL	K0003	/AC SHOULD EQUAL 7777
2476	7042	CMA		
2477	7442	SZA		/AC SHOULD BE ZERO
2500	7402	HL!		/AUTO INDEX ERROR
		/AJTO INDEX	TEST 163	
2501	7200	CLA		
2502	1032		K7767	/CONSTANT TO BE INDEXED
2503	3017	DC.	-	
2504	0417		1 1/	/DO AUTO INDEX
2505	1017	TA~		
2506	1046	·	K0007	/AC SHOULD EQUAL 7777
2507	7040	CMA		
2510	7440	SZA		/AC SHOULD BE ZERO
2511	7422	HL!		/AUTO INDEX ERROR
		/AUTO INDEX	TEST 104	
2512	7200	CLA	1-31 1-1	
2513	1031	- ···	ĸ7757	/CONSTANT TO BE INDEXED
2513	3017	DÇA		, qq, qq, q,
2515	0417		1 17	/DO AUTO INDEX
2516	1017	TAU		
	1045		K0017	AC SHOULD EQUAL 7777
2517	7040	CM⇒	Umn4,	Me endess session in
2520	7440	S ≠ ₩		/AC SHOULD BE ZERO
2521	7402	HLT		/AUTO INDEX ERROR
2522	1786	761		AUDIA FAMMU MUUAU

			X TEST 105	
2523	7200	۵۲	A - κ7737	ACOMPTANT TO BE IMPEMED
2524 2525	1027 3017	I A	A 17	/CONSTANT TO BE INDEXED
2526	Ø417		D I 17	/DO AUTO INDEX
2527	1017		D 17	
2530	1244	•	D K0037	/AC SHOULD EQUAL 7777
2531	7340	CM		AC CHANGE OF TERM
2532 2533	7440 7402	S Z HL		/AC SHOULD BE ZERO /AUTO INDEX ERROR
2933	7402	F &	•	, 40 10 INDEX CHAON
		/AJTO INDE		
2534	7200	ĞĖ		AGONOTANT TO DE INDENED
2535	1026	T A DC	≽ κ7677 Α 1 ⁷	/CONSTANT TO BE INDEXED
2536 2537	30 ₁ 7 0417			/DO AUTO INDEX
2540	1017		£ 17	
2541	1043		₽ K0077	/AC SHOULD EQUAL 7777
2542	7040	CM		AC CUAH D DE ZEDA
2543	7440	SZ HL		/AC SHOULD BE ZERO /AUTO INDEX ERROR
2544	7402	P.L.	1	ANDIO THANK THANK
		/AUTO INDE	X TEST 107	
2545	7200	CL		400000 WD WD WD ANDENED
2546	1025		D K7577	CONSTANT TO BE INDEXED
2547 2552	3017 0417		A 17 - I 17	/DO AUTO INDEX
2551	1017	The state of the s	- 17	
2552	1042		U KØ177	/AC SHOULD EQUAL 7777
2553	7040	CM		ALC DUALID DE TERR
2554	7440	S ź HL		/AC SHOULD BE ZERO /AUTO INDEX ERROR
2555	7402	7 L	i	NAGIO IMPEN ENVON
		/AUTO INDE	X TEST 108	
2556	7200	CL	A	
2557	1024		0 K7377	/CONSTANT TO BE INDEXED
2560	3017		A 17 ₩ I 17	/DO AUTO INDEX
2561 - 2562	0417 1017			PUD NOTO LITUEN
2563	1041		₩ KØ377	/AC SHOULD EQUAL 7777
2564	7040	CM		
2565	7440	S₹		/AC SHOULD BE ZERO /AUTO INDEX ERROR
2566	7402	HL	Ť	NADIO TAREX EKKOK
		/AUTO INDE	A TEST 109	
2567	7200	CL		
2570	1023		ж K6777	/CONSTANT TO BE INDEXED
2571	3017		A 17	ADD AUTO TAINEY
2572 2573	2417		D [1/ D 1/	VDO AUTO INNEX
2573 2574	1017 1040		L K0777	/AC SHOULD EQUAL 7777
2575	7040	CM		
257€	7442	S £		/AC SHOULD BE ZERO
2577	7402	» <u> </u>	1	/AUTO INDEX ERROR

	2000	X3C/1 (1 A\ X3C/1 (1 A\	TEST 110	
	122	CLA	45777	ZCONSTANT TO BE INDEXED
	1722		1/	100 40 1 4 4 5 5 5 4 4 5 5 K 5 K 5 K 5 K 5 K 5 K
	3 17 2417		1 17	/DO AUTO INUEX
	7320	40h		
2625	1917	1 A J		
2636	1/3/	CAT	K1777	/AC SHOULD EQUAL 1777
2637	7)40	CMA		
	7443	SEA		/AC SHOULD BE ZERO
2611	74.12	러노T		ZÄÜTO INDEX ERROR
		XaCyl CTLAN	TEST 111	
2412	7200	SLA		
	1 121		K3777	CONSTANT TO BE INDEXED
	30 <u>±</u> 7		17	
	3417		1 17	/UO AUTO INDEX
2616	1.117	IAU	-	/AC SHOULD EQUAL 7777
2617	1321	CMA CMA	43777	AC SHOULD EGOAL ////
	7 140	SZA		/AC SHOULD BE FERO
	7442	3 24 4LT		ZAUTO INDEX ERROR
2522	74)2	· ·		7,4010 14324 24 30
		VALVI OT AV		
	7261	JLA		ADDICTANT TO SE IMPEVED
2624	1/150		K77/7	CONSTANT TO BE INDEXED
	5)17		17	/OO AUTO INDEX
	341/	·	I 17 17	750 40.0 INDEX
	1:17		K7777	/AC SHOULD EQUAL 7777
	1 120	CMA		
	7 143 7443	S £ A		ZAC SHOULD BE ZERO
2433	7432	4_T		ZAUTO INDEX ERROR
		ZAUTO INDEX	TEST 113	
2534	23°	JMH	.+2	
	7+32	4 L T		/JMP FAILED
2434	7+ <u>4</u> 2	5.5.2		/JMP WORKED (A LITTLE)
	2544	204		
2541	125/		1	
	3 1 1		10	/TEST INSTRUCTION
	5 11 1	J.4P	I 16	/JMP INDIRECT FAILED
-	, ; ; ;	HLI		/LOCATION 2610. NO INDEX
2544	1.2			/IN WTI STATE,

```
/AUTO LYDEA TEST 114
                                 34, cru
2445 4:41
                                 461
                                                 JUMS FAILED
2046 74 E
                                                 /JMS FAILED
                                 FILL
1647
      14.7
                                 1AJ .-1
645 1 2500
                                 SKP
2651 7:15
                                  . - 4
2652 20-0
                                 LIA
2653 7 41
                                 1AU .-2
2654 1252
                                 SZA
2555 7446
                                                  /WRONG ADDRESS STORED
2656 14.2
                                 FLI
                                                  JULIRING JMS
                                 SKP
                                                  /JMS WORKS (I GUESS)
2657 7-10
                                  ,+4
2665 2704
                                 TAU .-1
2601 1260
                                 LCA 12
2662 3 11
                                                          /TEST INSTRUCTION
                                 UMS I 10
2663 441.
                                                 JJMS FAILED
                                 HLI
2664 1422
                                                 JUMS FAILED
                                 HLI
2465 7472
                                 140 .-1
2565 1650
                                 SAP
2007 7416
                                 , -4
2677 2064
                                 CIA
2671 7.141
                                 1AU .-2
2672 1270
2673 744.
                                 SZA
                                                 /WRUNG AUDRESS STORED DURING JMS
                                 ril I
2674 14, 2
                         /I TERRUPT TEST 1
                                 JMS ! .+1
2675 4070
                                                          /RUBOUT CHARACTER
                                 STR
2676 4 11
                                 1 SF
2677 0 41
                                 TLS
2723 5 46
2721 6 41
                                 151
27:2 53.1
                                 WH .-1
                                 LLA
2763 72...
                                                        /FLAG IS UN
                                 TAU SACKI
27.4 1312
                                 UCA 2
2725 3 2
                                 10 v
27:6 6 .1
                                                         /GO TO LOC 0000
                                 VUP
2717 7 73
                                                ZHO INTERRUPT
                                 HLI
2717 70 3
                                 .-1
2/11 671
                         1.11.
                         MACK!:
                                 , + 1
2712 8125
                                                 /HETURN FROM LOC 1
2125 2700
                                 EZA
2/14 7-62
                                 -- L T
                                                 VAC SHOULD BE 6
                                                 JUDINE IDE YOU CHECK
                                 1AU 2
2715 1 3
                                 CLA
21:0 1 1.
                                 JA . Buf1
2/17 1:11
                                 SEA JLA
116.
                                                 JINTERRUPT ERROR
2172 16 6
                                 -- _ 1
                                                 /ARUNG ADDRESS STURED
```

The second secon

	3 %	*3.00 /[TERRUFT TEST 4	
		TAU K. 3//	/RUBOUT CHARACTER
	<u>i</u> v 44 i	151	
3- 21	5, +1 5, 46	145	
		TSF	
	6.41	1 • ، • 1	
-	52.3	CLA	/FLAG IS ON
	12.	TAU BACK4	
31106	1215	JCA 2	
3~ ₫7	3. 12	1AU K77/7	
-	1.24	NCI	
	6.01	DCA 3	
	3. 4 5	h_1	INO INTERRUPT
	14,12	njt4,1	
~ -	3,713	BACK4 . +1	
•	3,16	5 £ A	/RETURN FROM LOC1
· -	764.	PL T	/JONFIDENCE CHECK
3 17	74.12	-	/AC SHOULD BE FERO
3:12.1	<u>1</u> 1.23	1AU 3	
	77.40	CHA	
	744.	SZA	TO THE TO THE POURT
3023	74.52	HLT	/JCA PRIOR TO INTERRUPT /railed
2011.4	37.13	UCA 3	
3924		TAJ Ø	
.,	1 1 Ju 7 0 4 1	CIA	
	1214	TAU OUT4	
3027	754	SZA CLA	
3031 3031	74.12	HLT	/INTERRUPT ERROR /4RONG ADDRESS STORED
		/INTERRUPT TEST 5	
3732	1.141	TAU K#3/7	ZRUBOUT CHARACTER
3/33	5 41	131	
	5, 45	ILS	
3-35	5.41	154	
3/35 3/36	5232	J 7P1	
	7213	C A	/FLAG IS ON
	1250	TAU BACKS	
_	\$ 12.50 \$ 12.50	UCA 2	
	1.07	TAU 477/6	
5.42	1.00		

PAGE +

3 47	3. , 3	UCA 3	
	6.1	โอง	
5 45	2	15± 3	
	74.2	mu l	ZNO INTERRUPT
	3.40	(To, ,-1	,
3.5	3, 51	4AOK5, .+1	
	744s	SZA	/HETURN FROM LCC1
		HLT	/CONFIDENCE CHECK
3.27	74.2	'' <u>'</u>	/AC SHOULD BE ZERU
		TAU 3	AC SHOULD BE SENO
\$153	10,3	CmA	
	71.44	<u>- '</u>	
3 7 5		SŁA	4103 DD103 TD
3.156	742	HLT	/1SZ PRIOR TO
			/INTERRUPT FAILED
3757	3× £3	UCA 3	
	1766	TAD 3	
	71 41	CIA	
3.62	124/	כדטט טאו	
3. 63	7642	SZA CLA	
5 04	7-22	HLT	/INTERRUPT ERROR
			/WRONG ADDRESS STORED
		/INTERRUFT TEST 6	
3.05	1/41	TAU KU3/7	/RUBOUT CHARACTER
3. 66	6841	1 S F	
	01'46	165	
3(1)		1SF	
-	2274	JMP1	
	124 c	CLA	/FLAG IS ON
5///	1 1 1 1	O L, T	
-			,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
3 173	1304	TAD HACK6 DCA 2	,, Eno 10 0 .
3 173 3174	1344 3648	TAD HACK6 UCA 2	,, ene 18 a ·
3 173 3174 3175	1324 3892 1722	1AD BACK6	,, ene 18 a ·
3 173 3174 3175 3176	1304 3802 1722 3733	1AD BACK6 UCA 2 1AD 47777 UCA 3	,, ene 18 a ·
3 173 3174 3175 3176 3177	1304 3692 1722 3733 6731	1AD BACK6 DCA 2 1AD 47777 DCA 3 10N	,, ,,,
3 173 3174 3175 3176 3177 31x1	1324 3492 1722 3433 6731 2473	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 152 3	
3 173 3774 3175 3176 3177 3111	1304 3692 1722 3733 6731 2733 7402	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15± 3	ZNO INTERRUPT
3:73 3:74 3:75 3:76 3:76 3:77 31:1 31:1	1304 3692 1722 3733 6731 273 7482 7482	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15± 3 HET	
3 173 5 174 5 175 3 176 3 177 5 1 1 1 3 1 1 2 5 1 1 3	1324 3892 1722 3733 6731 273 7482 7482 3182	1AD BACK6 UCA 2 1AU K7777 UCA 3 10N 15± 5 HL1 HL1 OUTO,1	
3 177 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4	1324 3892 1722 3733 6731 273 7402 7402 7402 3102 3103	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15z 5 HL1 HLT OUTO, -1 HACKO, +1	ZNO INTERRUPT
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5	1344 3492 1722 3733 6731 273 7442 7442 3142 3143	1AD BACK6 UCA 2 1AD K7777 UCA 3 10N 15z 3 HL1 HLT 0UTO, -1 HACK6, +1 SEA	ZNO INTERRUPT ZHETURN FROM LOC 1
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5	1324 3892 1722 3733 6731 273 7442 7442 3142 3143	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15z 5 HL1 HLT OUTO, -1 HACKO, +1	ZNO INTERRUPT ZHETURN FROM LOC 1 ZOONFIDENCE CHECK
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5 5 1 1 6	1344 3492 1722 3733 6731 273 7442 7442 3143 7444 7444	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15z 3 HL1 HLT HLT HLT HACK6, +1 SZA HLI	ZNO INTERRUPT ZHETURN FROM LOC 1
3 173 3 174 3 175 3 176 3 177 3 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5 5 1 1 6	1344 3492 1722 3733 671 273 7442 7442 5145 7444 7447	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15z 3 HL1 HLT OLTO, -1 HACK6, +1 SZA HL1	ZNO INTERRUPT ZHETURN FROM LOC 1 ZOONFIDENCE CHECK
3 173 3 174 3 175 3 176 3 177 3 171 3 171 3 172 3 173 5 173 5 175 5 177 5 117	1344 3492 1722 3733 671 273 7442 7442 5143 7444 7444	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15z 5 HL1 HLT OLTO,1 HACKO, +1 SZA HL1 1AU 3 SZA	/NO INTERRUPT /HETURN FROM LOC 1 /CONFIDENCE CHECK /AC SHOULD BE ZERO
3 173 3 174 3 175 3 176 3 177 3 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5 5 1 1 7 5 1 1	1344 3492 1722 3733 671 273 7442 7442 5145 7444 7447	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 15z 3 HL1 HLT OLTO, -1 HACK6, +1 SZA HL1	ZNO INTERRUPT ZHETURN FROM LOC 1 ZOONFIDENCE CHECK ZAC SHOULD BE ZERU ZISZ PRIOR TO
3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5 5 1 1 7 5 1 1 1	1304 3604 3602 1022 3003 602 2003 7402 7402 3103 7402 7402 7402 7402	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 152 3 HL1 HLT OLTO, -1 HACK6, +1 54A HL1 1AD 3 54A HL1	/NO INTERRUPT /HETURN FROM LOC 1 /CONFIDENCE CHECK /AC SHOULD BE ZERO
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5 3 1 1 1 3 1 1 1 3 1 1 1 3 1 1 1 3 1 1 1	1304 3492 1 · 22 34 · 43 6 · 21 24 · 23 74 · 22 31 · 23 74 · 2 31 · 2 74 · 2 31 · 3 74 · 3	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 152 3 HL1 HLT OLTO, -1 HACK6, +1 54A HL1 1AD 3 54A HL1	ZNO INTERRUPT ZHETURN FROM LOC 1 ZOONFIDENCE CHECK ZAC SHOULD BE ZERU ZISZ PRIOR TO
3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 5 5 1 1 7 5 1 1 1	1304 3892 1 128 3893 6 11 26 33 7402 7402 7402 7402 7402 7402 7402 7402	1AD BACK6 DCA 2 1AD K7777 DCA 3 10N 152 3 HL1 HLT OLTO, -1 HACKO, +1 54A HL1 1AD 3 54A HL1 1AD 3 54A HL1	ZNO INTERRUPT ZHETURN FROM LOC 1 ZOONFIDENCE CHECK ZAC SHOULD BE ZERU ZISZ PRIOR TO
3 173 3 174 3 175 3 176 3 177 3 171 3 172 3 173 3 174 3 175 5 1 17 5 1 17 5 1 17 5 1 17 5 1 17 5 1 17	1304 3692 1722 5743 673 273 7402 74	1AD BACK6 DCA 2 1AD K7777 DCA 5 1DN 152 5 HL1 HLT 0.10, -1 HACK6, +1 54A HL1 1AD 3 54A HL1 1AD 3 54A HL1 1AD 3	ZNO INTERRUPT ZHETURN FROM LOC 1 ZOONFIDENCE CHECK ZAC SHOULD BE ZERU ZISZ PRIOR TO
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 1 5 1 1 1 1	1304 3692 1 122 54 13 6 11 24 13 74 12 74 12 31 15 74 17 74 12 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1AD BACK6 DCA 2 1AD K7777 DCA 5 10N 152 5 HL1 HLT OUTO,1 HACK6, +1 52A HL1 1AD 3 52A HL1 DCA 3 1AD Ø C1A TAD OUTO	ZNO INTERRUPT ZHETURN FROM LOC 1 ZOONFIDENCE CHECK ZAC SHOULD BE ZERU ZISZ PRIOR TO
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 1 5 1 1 1 1	1304 3692 1722 5743 673 273 7402 74	1AD BACK6 DCA 2 1AD K7777 DCA 5 10N 152 5 HL1 HL1 OUTO, -1 HACKO, +1 52A HL1 1AU 3 52A HL1 JCA 5 1AU Ø G1A TAU OUTO 52A CLA	/NO INTERRUPT /HETURN FROM LOC 1 /CONFIDENCE CHECK /AC SHOULD BE ZERO /ISZ PRIOR TO /INTERRUPT FAILED
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 1 5 1 1 1 1	1304 3692 1 122 54 13 6 11 24 13 74 12 74 12 31 15 74 17 74 12 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1AD BACK6 DCA 2 1AD K7777 DCA 5 10N 152 5 HL1 HLT OUTO,1 HACK6, +1 52A HL1 1AD 3 52A HL1 DCA 3 1AD Ø C1A TAD OUTO	/NO INTERRUPT /RETURN FROM LOC 1 /CONFIDENCE CHECK /AC SHOULD BE ZERO /ISZ PRIOR TO /INTERRUPT FAILED
3 173 3 174 3 175 3 176 3 177 3 1 1 1 3 1 1 2 3 1 1 3 3 1 1 4 3 1 1 1 5 1 1 1 1	1304 3692 1 122 54 13 6 11 24 13 74 12 74 12 31 15 74 14 74 12 3 1 14 74 12 3 1 14 74 12 3 1 14 74 12 3 1 14 74 12 74 12	1AD BACK6 DCA 2 1AD K7777 DCA 5 10N 152 5 HL1 HL1 OUTO, -1 HACKO, +1 52A HL1 1AU 3 52A HL1 JCA 5 1AU Ø G1A TAU OUTO 52A CLA	/NO INTERRUPT /HETURN FROM LOC 1 /CONFIDENCE CHECK /AC SHOULD BE ZERO /ISZ PRIOR TO /INTERRUPT FAILED

```
/I HERRUPT TEST /
                                                       /RUBOUT CHARACTER
                                 TAD NESTI
312 1.41
                                 TSF
3121 0 41
                                 11,5
5122 0 40
                                 151
3123 . 41
                                 JAP .-1
5124 5 20
                                                 /FLAG IS ON
3125 7238
                                 CLA
                                 TAU PACK7
3126 1334
                                 LCA Z
3127 3 02
                                 PUL
313: 0 11
3131 5 31
                                 JMF .
                                                 INC INTERRUPT
                                 HLT
3132 7472
                         6cT7.
                                 .-2
3133 3131
                                 .+1
                         BACK7,
5154 5155
                                                 VRETURN FROM LOC 1
                                 SZA
3135 7446
                                 HLT
                                                 /LONFIDENCE CHECK
3136 1-12
                                                 1AC SHOULD HE E
                                 C UAT
3137 12kg
                                 CIA
3140 7 41
                                 TAU OUT/
3141 1333
                                 SZA CLA
3142 7540
                                                 /INTERRUPT ERROR
3143 75,2
                                 HLI
                                                 /WRONG ADDRESS STORED
                         /INTERRUPT TEST B
                                                       /RUBOUT CHARACTER
                                 TAU K2317
5144 1.41
                                 TSF
3145 0.42
                                 TLS
3144 5 146
                                 TSF
3147 6341
                                 JAP .-1
315: 5347
                                                 /FLAG IS ON
                                 CLA
3151 /20
                                 TAU BACKB
3152 1362
                                 JCA 2
3153 3432
                                 NCI
3154 6 21
3105 4 133
                                 JM5 3
                                                 INTERRUPT
                                 HLI
3154 7442
                         jul8,
                                 .-1
3157 3150
                                 . + 1
                         BACK8,
3161 3161
                                                 VRETURN FROM LOC 1
                                 SZA
3161 744"
                                                 100 VFIDENCE CHECK
3102 7702
                                 HL1
                                                 JAC SHOULD BE FERD
                                 TAU 5
51K5 13.5
                                ULA
51:54 7:41
                                TAI OUTB
3100 115/
                                 SZA
3100 7442
                                                 /JMS ERRUR PRIOR
                                 MET
3107 .4 2
                                                 , TO INTERRUPT WRONG
                                                 JADURESS STURED
```

PAGL

```
140 3
114 4
140 44
111 014
```

3177 31/1 31/2 31/3 31/4

/INTERPUPT ERROR /WRONG ADDRESS STORED

7 7 7 0 0 0 0 1 1

31/5 31/5 31/7

```
* 5200
     12:1
                         11 TERRUPT TEST 9
                                                       ZRUBOUT CHARACTER
                                1A) K33//
5201 1141
                                 15+
32.1 - 42
                                 11.5
32 2 6 40
                                 151
3223 2141
                                 JM3 .-1
32-4 52 5
                                                 /FLAG IS ON
                                 CLA
3265 1266
                                 TAU BACKS
3226 _2212
                                 JCA 2
52,7 3.12
                                 1AU K7717
3211 1127
                                 104
3211 6 75
                                 CLA
3212 721
                                                140 INTERRUPT
                                 4LT
3213 14.2
                         0.119,
                                 .-1
3214 3213
                                 , +1
                         34CK9:
3215 3210
                                                 /RETURN FROM LOC 1
                                 SEA
3216 1441
                                                /CLA PRIUR TO INTERRUPT
                                 HLT
3217 14 2
                                                 1+ A LED
                                 TAD 3
322 1 . 14.6
                                 CIA
3221 7 -41
                                 TAU OUT9
3222 1214
                                 SZA CLA
3223 764.
                                                 /INTERRUPT FAILED
                                 HLT
3224 74,2
                                                 INRUNG ADDRESS STORED
                         /I TERRUPT TEST 15
                                                        /RUBOUT CHARACTER
                                 TAU K23/7
3225 1/41
                                 TSF
3726 0141
                                 ILS
3227 11 45
                                 151
323 0141
                                 JMP , -1
3231 5231
                                                 /FLAG IS ON
                                 LLA
3232 7201
                                 TAU BACKIZ
3233 _2242
                                 DCA S
3234 36.2
                                 IUV
3235 51.1
                                 TSF
5236 MAL
                                 HLI
                                                 INTERRUPT
3237 7402
                                 mL !
324 1 / 12 =
```

			*	
3241	3240	- OJT10,1	•	
		SACK10, .+1		
3242				
3243	フチキシ	S##	L	TRETURN FROM LOC 1
	74.02	H_1		/CONFIDENCE CHECK
3244	1906	1		
				/AC SHOULD BE FERO
3245	(و بها څخ او د	TAL	λ (
3246	7241	UIA		
3247	_241	TAL	00110	
-			CLA	
	7640			
3251	7492	HLI		/INTERRUPT ERROR
	-			/WRONG ADDRESS STORED
				, into the Assituate Station
		/1 STERRUPT	TEST 11	
105.5	"1 -1	1 4 1	1 KØ3/7	/RUBOUT CHARACTER
3252	⊥B41			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
3253	6741	TSF		
3254	5046	TLS		
3255	5741	131		
3256	>255	JMF	1	
	- · · ·			/FLAG IS ON
3257	7200	CLA		/ LL MG 13 04
3260	₁ 3 ₁ 7	TAL	HACK11	
		J C A		
3201	3002			
3262	6991	101	ŀ	
3203	იპა2	101		
		134		
3204	o331			
3265	ച്ച2	106		
-	5001	103	ł	
•				
3267	5332	101		
3273	6491	IUV	1	
		101		
32/1	o∂⊌2			
3272	าทิป1	109		
3273	5002	101		
3274	5001	101		
3215	5002	171		
		401	i	
3276	50.71			
3277	52.32	10+		
3300	o∂01	104	ł	
-		IUF		
3391	52.32			
3302	00J1	100	1	
		101		
3 363	0732			
33£4	or 01	104		
3 425	27.75	10+		
		198	ı	
-	30 12			
3327	5 4.2	1 1+		
	3.54	I+1.5	i	
	33.3	101		
3 < 12	56 1	104	1	
		1.11		
3313	5302	• • •		

```
TSF
3314 5741
                                                 INHAT HAPPENED TO MY FLAG
3415 7412
                                 MLT
                                 SKP
33.4 7410
                         BACK11, ,+2
3317 3321
332 7413
                                 SKH
                                                 /INTERRUPT OCCURRED DURING
                                 HLI
3321 7432
                                                 /ION-IOF SEQUENCE
                                                 ISEE LOCATION ENDU
                         /INTERRUPT TEST 12
                                                 /CLEAR FLAG
                                 TOF
3322 5342
3323 1234
                                 CLA
                                 TAU BACK12
3324 1334
                                 JCA 2
3325 3032
3326 5031
                                 N.C.I
                                 4CV
3327 7030
                                 NUP
3334 7/133
                                 NUP
3331 7000
3332 7034
                                 NJP
                                 SKP
3533 7410
                         BACK12, ,+2
3334 3336
                                 SKP
3335 7410
                                                 /INTERRUPT WITH NO
3336 7422
                                 HLT
                                                 IFLAG.
                                 TOF
3337 6222
                         /ILLEGAL AUTO INDEX TEST1
3340 7230
                                 CLA
                                 JAP 1 ,+1
3341 5742
                                 ANU1
3342 4433
                         K4810, 4010
3343 4010
      +130
                         *4000
                                                       /TEST INSTRUCTION
                                 ANU I 4010
                         A v . 1 .
4737 '510
                                 JMP I .+1
4001 2622
                                 HET1
4202 3350
      5350
                         *3350
                                 TAU 1 K4810
3351 1745
                         RET1.
3351 7442
                                 5 £ A
                                 HLT
                                                /ERROR, AC SHOULD BE ZERO
3352 7462
                                                 /ANU 1 4010 ALTERED (4010)
                                 LLA
3353 7270
                                 UCA I 44010
3354 5743
```

3,5

VILLEGAL ANTO INDEX TEST 2

3355 3356 3357 3360	7200 5757 2173 2010	K20 10 ,	JMF I AN=2 2010	.+1	
2173 2174 2175	2173 0610 5775 3370	*2173 AND2,	ANU I JMF I RE12		/TEST INSTRUCTION
3370 3371 3372 3373 3374	3370 1760 7440 74 ₀ 2 5774 3400	*3370 RET2,	TAB I SZ& HL! JMP I 3480	K2010	/ERROR. AC SHOULD BE ZERO /AND I 2010 ALTERED (2010)
3400 3401 3402 3403	3400 7200 5602 1173 1010	/ILLEGA #3400	CLA JMP I AND3 10 0		TEST 3
1173 1174 1175	1173 0610 5775 3410	*1173 AND3;	AND I JMP I RETS		/TEST INSTRUCTION
3410 3411 3412 3413	3410 1603 7440 74 ₀ 2 7200	*3410 RET3,	TAD I S#- HLT	K1010	/ERROR. AC SHOULD BE ZERO /AND I 1010 ALTERED (1010)
3414	3603			K1010	

/ILLEGAL AUTO INDEX TEST 4

3415 3416 3417 3420	7200 5617 0574 0410	K410,	CLA JMP I .+1 ANU4 41#	
0574 0575 0576	Ø574 Ø610 5776 3430	*574 AND4;	AND I 410 JMM I ,+1 RE!4	/TEST INSTRUCTION
343Ø 3431 3432	3430 1620 7440 7402	#3430 RET4,	TAD I K410 SZA HLT	/ERROR. AC SHOULD BE ZERO /AND I 410 ALTERED (410)
3433 3434	7200 3620		CLA DC- I K410	
		/ILLEGA	L AUTO INDEX TE	ST 5
3435 3436 3437 3440	7200 5637 0371 0210	K210,	CLA JM [*] I .+1 AND5 21-	
0370 0371 0372 0373	0370 5374 0610 5773 3450	*370	JMF .+4 AN 1 210 JMP I .+1 RET5	/TEST INSTRUCTION
3450 3451 3452	3450 1640 7440 7402	#3450 RET5,	TAD I K210 SZA HLT	/ERROR. AC SHOULD BE ZERO /AND I 210 ALTERED (210)
3453 3454	7200 3640		DCA I K210	

/ILLEGAL AUTO INDEX TEST 6

3455 3456 3457 3460	7200 5657 0130 0110	K110.	CLA JMP I .+1 AN¤6 11#	
0130 0131 0132	0130 0510 5532 3470	*13Ø ANj6,	ANU I 110 JMP I .+1 REI6	/TEST INSTRUCTION
3470 3471 3472 3473 3474	3470 1660 7440 7402 7200 3110	*3470 RET6,	TAD K110 SZA HL! CLA DCA 110	/ERROR, AC SHOULD BE ZERO /AND I 110 ALTERED (110)
3475 3476 3477	7200 5677 0124	/ILLEGA	CLA JMP I .+1 ANU7 50	ST 7
3500 0124 0125 0126	0050 0124 0450 5526 3510	*124 AND7,	ANU I 50 JMP I .+1 RE17	/TEST INSTRUCTION
3510 3511 3512 3513 3514	3510 1700 7440 7402 7200 3050	*3510 RET7,	TAN I K50 Sin HL: Cla DC4 50	/ERROR. AC SHOULD BE ZERO /AND I 50 ALTERED (50)

/ILLEGAL AUTO INDEX TEST 8

3515 3516 3517 3520	7200 5717 0120 0030	K32,	CLA JMF I .+1 ANU8 30	
Ø12Ø Ø121 Ø122	0120 0430 5522 3530	#12Ø ANJ8,	ANU I 30 JMP I .+1 RE18	/TEST INSTRUCTION
3530 3531 3532 3533	3530 1720 7440 7402 7200	*3530 RET8,	TAU ; K30 SEA HLT CLA	/ERROR. AC SHOULD BE ZERO /AND I 30 ALTERED (30)
3534	3030	/ILLEGA	DCA 30 L AUTO INDEX TES	ST 9
3535 3536	7200 3000		CLA DCA Ø	
3537 3540	5740 0074		JM : 1 ,+1 AND9	
		*74 AND9,		/TEST INSTRUCTION
3540 0074 0075	0074 0074 0400 5476		AND I Ø JM I +1	/TEST INSTRUCTION /ERROR, AC SHOULD BE ZERO /AND I Ø ALTERED (Ø)

PAC:

```
/ILLEGAL AUTO INDEX TEST 10
                                 CLA
3555 7200
                                 JM# 1 . +1
3556 5757
                                 ANU10
3557 0070
                         #72
      0070
                                                 /TEST INSTRUCTION
                         AVJ10,
                                 ANP I 7
0070 0407
                                 JM# 1 .+1
0071 5472
                                 RE 110
0072 3600
                         #3600
      3600
                         RET10.
                                 TAD I KU007
3600 1446
                                 SZM
3601 7440
                                                 /ERROR. AC SHOULD BE ZERO
                                 HL I
3602 7402
                                                 /AND I 7 ALTERED (7)
                                 CL#
3603 7200
                                 DCA 7
3604 3007
                         /CHECK FOR TTY BELL
                                 TAM BLCNT
3605 1223
                                 IA
3606 7001
                                 DC# BLCNT
36g7 3223
                                 TAD BLCNT
3610 1223
                                 TAP RNGCNT
3611 1224
                                 SZA CLA
3612 7640
                                 JMP I K201
3613 5622
                                 DCA BLONT
3614 3223
                                 TAU BELCOD
3615 1225
                                 TL-
3616 6046
                                 TSF
3617 6041
                                 JMP .=1
3620 5217
                                 JMP : . +1
3621 5622
                         K201,
                                 201
3622 0201
                         BLCNT: 0
3623 0000
                         RNGCNT, -50
3624 7730
                         BELCOU. 207
3625 0207
      4010
                         *4210
                                 0
4010 0000
                         STP,
4011 0000
                                 TAW JMPIX
4012 1221
                                 DC8 1
4013 3001
                                 DCA 2
4014 3002
                                 DC 3
4015 3003
                                 TAD K0377
4016 1041
                                 IS# STR
4017 2211
                                 JMP I STR
4020 5611
                         JMP 1X, 5402
```

\$

4021 5402

SYMBOL TABLE

K4010	3343
K410	3420
K4400	0052
K4444	0056
K4577	0053
K50	3500
K20	0061
K5252	ØØ63
K5555	
K5777	0022
K6666	0055
K6777	0023
K7070	0057
K7377	0024
K7577	0025
K7677	0026
K7737	0027
K7757	0031
K7767	0032
K7773	0033
K7775	0034
K7776	0035
K7777	0020
01	2710
0 _{UT} 1 0UT1Ø	3241
OUT2	2762
	2734
OUT3	3014
OUT4	
OUTS	3047
OUT6	3103
OUT7	3133
OUT8	3157 3214
OUT9	3214
RET1	3350
RET10	3600
RET2 RET3	337Ø
RET3	3410 3430
RET4	3430
RETS	3450
RET6	3470
RET7	3510
RETS	3530
RET9	3550
RNGCNT	3550 3624
STR	4011
TPØ	0200
1 F W	0377
TP177	03//

SYMBOL TABLE

0020 0021 0022 K7777 K3777 K5777 0023 K6777 0024 K7377 K7577 0025 0026 K7677 0027 K7737 K7757 0031 0032 0033 0034 K7767 K7773 K7775 0035 0036 0037 K7776 KØ K1777 0040 K0777 0041 0042 KØ377 KØ177 0043 K0077 K0037 0044 0045 KØØ17 0046 KØØØ7 0047 K0003 0051 0052 0053 K0001 K4400 K4577 0054 K2525 0055 K6666 0056 K4444 0057 0060 K7070 K0707 0061 0062 0063 0064 0070 K5252 K1111 K5555 K4 AND10 AND9 0074 0120 AND8 0124 AND7 AND 6 0130 K176 0172 0173 0174 0175 K172 K173 K174 K175 0176 0177 0200 K1234 TPØ 0371 AND5 0377 0574 TP177 AND4 1173 2173 2710 AND3 AND2 OUT1

SYMBOL TABLE

BACK1	2711
OUT3	2734
BACK3	2735
OUT2	2762
BACK2	2763
OUT 4	3014
BACK4	3015
OUT5	3047
BACK5	3047 3050
DUT6	3103
BACK6	3104
OUT7	3133
BACK7	3133 3134
OUTS	3157
BACK8	3160
	3214
OUTS	3214
BACK9	3215
OUTIE	3241
BACK10	3242
BACK11	3317 3334
BACK12	3334
K4010	3343 3350
RET1	3350
K2010	336Ø 337Ø
RET2	3370
K1010	3403
RET3	3410
K410	3420
RET4	3430
RET4 K210	3440
KET5	3450
K110	3460
RET6	3470
K50	3500
	3510
RET7	3520
K30	3530
RETS	7550
RET9	3550
RET10	3600 3622
K201	3022
BLCNT	3623
RNGCNT	3624
BELCOD	3625
AND1	4000
STR	4011
JMPIX	4021

MAINDEC EVALUATION REQUEST

After sufficient familiarization with the operation and documentation of this MAINDEC, please indicate your assessment of the following areas and return this form to Digital Equipment Corporation. IDENTIFICATION: MAINDEC NO. ______ Program Title _____ USAGE: Used by: Field Service | Production | Other_____ Frequency of Usage: Daily Weekly Monthly SUGGESTIONS FOR IMPROVEMENT 1. Are the program loading and operating instructions: clear? , incomplete? , difficult to follow? 2. Do the error reports and program documentation provide sufficient diagnostic information. in all cases? , in most cases? , in very few cases? . Suggestions for improvement: 3. Is the program effective in isolating malfunctions: in all cases? , in most cases? , in very few cases? . Would additional Scope loops or Switch Register control be helpful?____ Suggestions for improvement: 4. Does the program ever fail to detect malfunctions exposed by other software?_____ Were Margins used?_____ Please describe malfunction in detail: 5. Does the program ever report non-existant malfunctions?_ Please indicate erroneous report and any pertinent operating conditions: 6. Does this MAINDEC ever expose malfunctions in the Central Processor or other peripheral units not detected by the appropriate MAINDEC? Please describe malfunction and MAINDEC(S) used: 7. Does the document provide a general understanding of the functional programming requirements of the system? Good, Fair, None. Would a general description of programming requirements increase the effectiveness of this MAINDEC? Remarks:

	Fold Here	
	Do Not Tear - Fold Here and Staple	
,		FIRST CLASS PERMIT NO. 33 MAYNARD, MASS
BUSINESS REPLY MAIL NO POSTAGE STAMP NECI	ESSARY IF MAILED IN THE UNITED STATES	
Postage will be paid by:	digital	
	Digital Equipment Corporation Diagnostic Programming Group	
	146 Main Street, Building 12 Maynard, Massachusetts 01754	