
(a)
Where was each side of the groins?
built
repaired
Gordon
last repair
Isabel
Buxton fill
Shoreline change since
1967 (m), + seaward
0
−50
−100
−150
−200
(b)
How wide was the gap between them?
155 m
1995
135 m
1996
74 m
2023
Gap (m)
north minus south
150
100
50
0
1970
1980
1990
2000
2010
2020
Year
north side (updrift), GIS 6
south side (downdrift), GIS 5
the gap: the groin's effect
structural losses reported, 2015-2021