
How strong is the groin each year in each option?
Strength: share of the drift the groin holds back
0.30
0.25
0.20
0.15
0.10
0.05
0.00
built
last repair
Isabel damage
2017 fill
2022 fill
south groin rebuilt
decay reported
1970
1980
1990
2000
2010
2020
calibration
test
2004 failure only (0.2, then 0.16), never off
three numbers: 0.2, 0.16 from 2004, off from 2017
two numbers: 0.2 (fitted to both records), off from 2017
two numbers: 0.16 (fitted to annual CoastSat), off from 2017