

Hatteras Island CASCADE Hindcast: Management Rules Summary (1984-2024)			
Location	CASCADE Domains	Period Active	Description
	Beach Nourishment Events — sediment added to specified domains		
Rodanthe	D85-88	2014	Emergency fill following storm erosion; material placed at southern Pea Island NWR boundary adjacent to Rodanthe (1,620,000 cy)
Buxton	D6-15	2022	USACE emergency shore-protection nourishment project
Avon	D23-26	2022	USACE emergency shore-protection nourishment project
	Road Relocation — Disabled Zones — NC-12 position held fixed		
Cape Hatteras	D1-6	1984-2024	No NC-12 road present; cape terminus with no through-road infrastructure
Buxton	D7-8	1984-2024	Developed community — dense built infrastructure prevents landward road relocation
Avon	D21-31	1984-2024	Developed community — dense built infrastructure prevents landward road relocation
Tri-Village (Salvo / Waves / Rodanthe)	D68-83	1984-2024	Developed community — dense built infrastructure prevents landward road relocation
N. Rodanthe / Pea Island NWR	D82-88	2022-2024	Jug Handle Bridge (July 2022): NC-12 permanently elevated off surface— road relocation physically impossible while bridge is in place

Note: Inter-village zones (D9-20, D32-67) retain road relocation capability throughout. Domain 1 = Cape Hatteras (south); Domain 90 = Oregon Inlet (north).