Requirements produtes Satety Policy - smooth oxelwation - over / under voltage - over temperature