
MOTOR CAR




MATERIAL REQUIRED



STICK GEAR MOTOR AND CUSTER WHEEL ON THE ICECREAM STICK AS SHOWN IN PICTURE




ATTACH WHEELS WITH GEAR MOTORS



JOIN WIRE AND BATTERY CAP WITH THE SWITCH AS SHOWN IN PICTURE

ARSHA SARAF'S LAB



ATTACH THE TWO ENDS OF WIRES WITH MOTOR AS SHOWN IN FIGURE



PLACED THE BATTERY ON THE ICECREAM STICK AND ATTACHED WITH BATTERY CAP AND MOTOR CAR IS READY

ARSHA SARAF'S LAB