

Facility Name: Coronado Generating Station

Facility Details

Facility ID (ORISPL): 6177 Monitoring Plan Location IDs: U2B State: AZ

County: Apache County
Year/Quarter: 2021 Q3
Total Hours: 2208

Evaluation Results

General Errors

Severity	Check Code / Result	Result Message
INFORM		The emissions quarterly report cannot be resubmitted until you contact the EPA for permission. After the EPA grants permission, you will need to log in to the EPA host system to retrieve the permission record. You will then need to reevaluate this file prior to submitting.

Hourly Data Errors

Unit/Stack/ Pipe	Severity	Check Code / Result	Result Message	Begin Date / Hour	End Date / Hour	Consecutive Hours
U2B	INFORM	HOURCV-39-G	Warning: The AdjustedHourlyValue reported in the DHV record for HI is in excess of the	07/01/2021 00	07/01/2021 00	1
			maximum value listed in the monitoring plan. Sources are required to periodically (at least once annually) evaluate the appropriateness of these maximum values in the	07/01/2021 11	07/01/2021 13	3
			include the need to update Span, Default, and/or Unit Capacity values. You should investigate the cause of these exceedances and determine whether adjustments to your monitoring systems or monitoring plan are necessary. 07/01/2021 21 07/01/2021 23 07/01/2021 23 07/02/2021 02 07/02/2021 04 07/02/2021 11 07/02/2021 11 07/02/2021 15 07/02/2021 15 07/02/2021 17 07/02/2021 17 07/02/2021 19 07/02/2021 19 07/02/2021 19 07/02/2021 19 07/02/2021 19	07/01/2021 19	1	
				investigate the cause of these exceedances and determine whether adjustments to your 07/01/2021 21 07/0	07/01/2021 21	1
					07/01/2021 23	1
				07/02/2021 02	1	
				07/02/2021 04	07/02/2021 05	2
				07/02/2021 11	07/02/2021 12	2
				07/02/2021 15	07/02/2021 15	1
				07/02/2021 17	07/02/2021 17	1
				07/02/2021 19	07/02/2021 19	1
				07/05/2021 16	07/05/2021 22	7
				07/06/2021 12	07/06/2021 15	4

September 9, 2022 02:43 PM

Facility Name: Coronado Generating Station

Facility ID (ORISPL): 6177

Unit/Stack/ Pipe	Severity	Check Code / Result	Result Message	Begin Date / Hour	End Date / Hour	Consecutive Hours
U2B	INFORM HOURCV-39-G	HOURCV-39-G	Warning: The AdjustedHourlyValue reported in the DHV record for HI is in excess of the maximum value listed in the monitoring plan. Sources are required to periodically (at least once annually) evaluate the appropriateness of these maximum values in the monitoring plan and make proper adjustments when necessary. Adjustments may include the need to update Span, Default, and/or Unit Capacity values. You should investigate the cause of these exceedances and determine whether adjustments to your monitoring systems or monitoring plan are necessary.	07/07/2021 00	07/07/2021 00	1
				07/07/2021 02	07/07/2021 03	2
				07/07/2021 13	07/07/2021 16	4
				07/07/2021 20	07/07/2021 22	3
				07/08/2021 00	07/08/2021 00	1
				07/08/2021 14	07/08/2021 15	2
				07/08/2021 18	07/09/2021 04	11
				07/09/2021 09	07/09/2021 11	3
				07/09/2021 13	07/09/2021 14	2
				07/09/2021 18	07/09/2021 20	3
				07/10/2021 04	07/10/2021 07	4
				07/10/2021 09	07/10/2021 12	4
				07/10/2021 15	07/10/2021 16	2
				07/10/2021 22	07/11/2021 02	5
				07/11/2021 13	07/11/2021 15	3
				07/11/2021 23	07/11/2021 23	1
				07/12/2021 05	07/12/2021 05	1
				07/12/2021 09	07/12/2021 11	3
				07/12/2021 13	07/12/2021 13	1
				07/12/2021 17	07/13/2021 01	9
				07/13/2021 03	07/13/2021 03	1
				07/13/2021 09	07/13/2021 12	4
				07/13/2021 14	07/13/2021 19	6
				07/13/2021 23	07/13/2021 23	1
				07/14/2021 01	07/14/2021 01	1
				07/14/2021 03	07/14/2021 05	3
				07/14/2021 14	07/14/2021 15	2
			07/14/2021 17	07/14/2021 17	1	

Emissions Evaluation Report

September 9, 2022 02:43 PM

Facility Name: Coronado Generating Station

Facility ID (ORISPL): 6177

Unit/Stack/ Pipe	Severity	Check Code / Result	Result Message	Begin Date / Hour	End Date / Hour	Consecutive Hours
U2B	INFORM	HOURCV-39-G	Warning: The AdjustedHourlyValue reported in the DHV record for HI is in excess of the maximum value listed in the monitoring plan. Sources are required to periodically (at least once annually) evaluate the appropriateness of these maximum values in the monitoring plan and make proper adjustments when necessary. Adjustments may include the need to update Span, Default, and/or Unit Capacity values. You should investigate the cause of these exceedances and determine whether adjustments to your monitoring systems or monitoring plan are necessary.	07/14/2021 19	07/14/2021 20	2
				08/24/2021 16	08/24/2021 22	7
				08/25/2021 01	08/25/2021 06	6
		MATSDHV-9-C	You reported MODC 39 for HGRE, but did not report both an output based MATS parameter and a Startup/Shutdown Flag.	07/30/2021 06	07/30/2021 09	4
		MATSDHV-9-B	You reported MODC 37 for SO2RH, but did not report both a heat-input based MATS parameter, and a Startup/Shutdown Flag.	07/30/2021 07	07/30/2021 09	3