



# **Facility Name: Hayden**

## **Facility Details**

Facility ID (ORISPL): 525
Monitoring Plan Location IDs: H1
State: CO

County: Routt County
Year/Quarter: 2021 Q4
Total Hours: 2208

### **Evaluation Results**

#### **General Errors**

Severity	Check Code / Result	Result Message		
INFORM		The emissions quarterly report cannot be resubmitted until you contact the EPA for permission. After the EPA grants permission, you will need to log in to the EPA host system to retrieve the permission record. You will then need to reevaluate this file prior to submitting.		

# **Hourly Data Errors**

Unit/Stack/ Pipe	Severity	Check Code / Result	Result Message	Begin Date / Hour	End Date / Hour	Consecutive Hours
H1	INFORM		You reported an MODCCode of 16 in the MHV record for SO2C, but the UnadjustedHourlyValue is equal to 2. According to Part 75.11(e)(3)(iii) any biasadjusted hourly average SO2 concentration of less than 2.0 ppm recorded by the SO2 monitoring system shall be adjusted to a default value of 2.0 ppm, for reporting purposes.	12/06/2021 05	12/08/2021 09	53