

Facility Name: River Valley

Facility Details

Facility ID (ORISPL): 10671

Monitoring Plan Location IDs: CS1, 1A, 1B, 2A, 2B

State: OK

County: Le Flore County
Year/Quarter: 2021 Q4
Total Hours: 2208

Evaluation Results

General Errors

Severity	Check Code / Result	Result Message			
INFORM		The emissions quarterly report cannot be resubmitted until you contact the EPA for permission. After the EPA grants permission, you will need to log in to the EPA host system to retrieve the permission record. You will then need to reevaluate this file prior to submitting.			

QA Status Errors

Unit/Stack/ Pipe	Category Description	Severity	Check Result	Result Message	Begin Date / Hour	End Date / Hour	Consecutive Hours
CS1	Leak Check Status Evaluation		RIT1 <u>OOC-Expired</u>	The prior leak check for Component ID 300 completed on 06/29/2021 has expired.	10/08/2021 00	10/08/2021 09	10
					10/11/2021 12	10/12/2021 09	22
					10/12/2021 14	10/19/2021 00	155
					10/19/2021 02	10/21/2021 18	65
					10/21/2021 23	10/21/2021 23	1
					10/22/2021 02	10/23/2021 00	23
					10/23/2021 02	10/24/2021 23	46
					10/25/2021 02	10/25/2021 03	2
					10/25/2021 05	10/25/2021 05	1
				10/25/2021 07	11/02/2021 16	202	
					11/03/2021 11	11/04/2021 15	29
					11/04/2021 23	11/05/2021 13	15
					11/05/2021 19	11/07/2021 13	43
					11/09/2021 13	12/15/2021 03	855

Emissions Evaluation Report

September 14, 2022 11:22 AM

Facility Name: River Valley

10671

Unit/Stack/ Pipe	Category Description	Severity	Check Result	Result Message	Begin Date / Hour	End Date / Hour	Consecutive Hours
CS1	Leak Check Status Evaluation	CRIT1		The prior leak check for Component ID 300 completed on 06/29/2021 has expired.	12/17/2021 13	12/22/2021 11	119

Hourly Data Errors

Facility ID (ORISPL):

Unit/Stack/ Pipe	Severity	Check Code / Result	Result Message	Begin Date / Hour	End Date / Hour	Consecutive Hours
CS1	INFORM		Warning: The UnadjustedHourlyValue reported in the DHV record for NOXR is in excess of the maximum value listed in the monitoring plan. Sources are required to periodically (at least once annually) evaluate the appropriateness of these maximum values in the monitoring plan and make proper adjustments when necessary. Adjustments may include the need to update Span and/or Default values. You should investigate the cause of these exceedances and determine whether adjustments to your monitoring systems or monitoring plan are necessary.	11/06/2021 06	11/06/2021 06	1