
Max Contact Pressure
Max Contact Pressure (kPa)
Scar Diameter (cm)
Percent Change in Max Contact Pressure
Percent Change in max CP
Contact Pressure Area
Contact Pressure Area (cm)
Percent Change in Contact Pressure Area
Percent Change CP Area
Average Contact Pressure
Average Contact Pressure (kPa)
Percent Change in Average Contact Pressure
Percent Change in avg CP
0.000 0.025 0.050 0.075 0.100 0.125 0.150
BCS_S
BCS_M
BCS_I