
Max Contact Pressure
Max CP (kPa)
% Change
Scar Diameter (cm)
Contact Area
Contact Area (cm)
% Change
Scar Diameter (cm)
Average Contact Pressure
Avg CP (kPa)
% Change
Scar Diameter (cm)
BCS_S
BCS_M
BCS_I