Issue detail

#81: Punch List

Status	Closed
Type	PL Field QC > Punch List



Standard fields

Description	Install missing lite at breakroom door
Assigned to	**DPR Doors Frames & Hardware - 10068779**
Created by	Luis Teran (DPR Construction)
Created on	Apr 25, 2025
Location	—
Location details	—
Due date	May 2, 2025
Start date	—
Placement	A2.1.2 (2ND FLOOR - CONSTRUCTION PLAN)
Root cause	—

Custom fields

Severity	—

Created ON Behalf of	—
Identify Corrective Measures performed by Responsible Party	—
Identify Opportunities for Improvement to prevent reoccurrence	—
DPRIssueType_FieldQC_Punchlist	—

References and Attachments

Photos (2)

20250425_082313_photo
Added as Reference
Taken on Apr 25, 2025, 5:23 AM HST
Added on Apr 25, 2025, 5:23 AM HST
Added by Luis Teran

20250502_080855_photo
Added as Reference
Taken on May 2, 2025, 5:08 AM HST
Added on May 2, 2025, 5:08 AM HST
Added by Luis Teran