
Medición PWM

TP-08 TIMER & PWM: EXAMPLE_8.1


Duty Cycle 0.5 for all R, G & B PWM.



Duty Cycle 0.5 for R PWM (G & B off)



Duty Cycle: R=0.8, G=0 & B=0.1



Duty Cycle: R=0, G=0.3 & B=0.6

