$$\frac{V_o}{V_o} = -\frac{R_2}{R_A} \qquad \qquad V_o = -\left(\frac{R_2}{R_A}V_A + \frac{R_2}{R_B}V_B + \frac{R_2}{R_C}V_C\right)$$
 Equation 1