

PT. RODAMAS MAKMUR MOTOR - HOLDING
JL. YOS SUDARSO (INDO MOBIL BATAM) SEI-BALOI LAUT
LUBUK BAJA-PANGKALAN PETAI
TELP : 0778-421206, FAX : 0778-421276

HAL : 1 / 1
TGL : 15-Dec-2025
JAM : 10:30:56
PID : SvRpTrn00101

PERKIRAAN BIAYA PERBAIKAN

Kepada Yth : PT.BATAM TEKNOLOGI GAS
JL BRIGJEND KATAMSO KM.03
KEM.TANJUNG PINCANG KEC.BATU AJI KOTA
BATAM
081373207513

Nomor : EST/25/000375
Tanggal : 15-Dec-2025
No Polisi : BP1802JQ
Model/Tipe : AVI414AT

Bersama ini kami sampaikan perkiraan biaya perbaikan kendaraan Bapak/Ibu dengan perincian sbb :

No.	Kode	Keterangan	Qty	Harga	Total
<u>Jasa Perbaikan</u>					
1	3A62R1	FRONT STRUT BOTH SIDE			480,000
2	PT00219	REAR SHOCK ABSORBER (BOTH SIDE)			360,000
					840,000
				Potongan :	0
<u>Penggantian Spare Parts</u>					
1	31601-77M11-000	STRUT ASSY,FR SUSPENSION RH	1.00	1,311,000.00	1,311,000
2	31602-77M11-000	STRUT ASSY,FR SUSPENSION LH	1.00	1,311,000.00	1,311,000
3	41710474L00-000	SUPPORT,FRONT STRUT	2.00	219,000.00	438,000
4	41800M60M01-000	ABSORBER ASSY,REAR SHOCK	2.00	732,500.00	1,465,000
					4,525,000
				Potongan :	0
				Jumlah :	5,365,000
				PPN (0.00 %)	0
				Total :	5,365,000

BATAM, 15-Dec-2025

Note : Perkiraan harga tersebut di atas sewaktu-waktu dapat berubah tanpa pemberitahuan lebih dahulu

(ADE CHANDRA ANDRIYANTO)
SERVICE ADVISOR