

PRESSURE VESSEL INSPECTION REPORT (ANNUAL)

Document ID: PV-2024-089-A | Date: 2024-03-15 | Inspector: QA/QC Lead

Finding 1: Flange bolt corrosion observed on downstream discharge nozzle N-2.

Finding 2: Ultrasonic thickness measurement on shell course 3 reads 11.8 mm (nominal: 12.0 mm, min required: 9.5 mm).

Finding 3: Pressure relief valve PRV-102 calibration seal intact; next inspection due in 60 days.

Finding 4: Minor paint blistering and surface oxidation detected on saddle support B.

Finding 5: Hydrostatic test pressure held at 18.5 bar for 45 minutes with zero measurable pressure drop.

Finding 6: Grounding lug continuity verified at 0.04 ohms resistance.