

CNC Lathe G71 Roughing Cycle Example

- CNC Lathe :
- DIA 50 mm
- OD
- 30 mm
- DIA 40 mm
- G71 Roughing Cycle
- 0.2 mm

G - code Program

```
%
O1001

G21
G18
G40
G99

T0101

G97 S800 M03
M08

G00 X52 Z2

G71 U0.2 R0.5
G71 P100 Q200 U0.2 W0.1 F0.25

N100
G00 X40 Z0
G01 Z-30

N200

G70 P100 Q200

G00 X100 Z100

M09
M05
M30
%
```

G21

millimeter

G18

Plane XZ

G40

Tool Nose Compensation

G99

Feed mm/rev

T0101

Tool 1 Offset 1

G97 S800 M03

 spindle 800 RPM

M08

 coolant

G00 X52 Z2

G71 U0.2 R0.5

Roughing Cycle 0.2 mm retract 0.5 mm

G71 P100 Q200 U0.2 W0.1 F0.25

 profile feed rate

G70 P100 Q200

Finish profile

M30

Summary

- :
- DIA 50 mm DIA 40 mm
 - 30 mm
 - Roughing G71
 - Finish G70