

control	Enable	Input	Output
		gain	Mode
values	On/Off	From 0 to	2_2_0,
		-∞ dB	2_2_1,
			2_0_0,
			3_2_0,
			3_2_1
default	On	-4 dB	2_2_0
value			

Tabela 1 – Korisničke kontrole