

control	Enable	Input	Headroo	Output
		gain	m gain	Mode
values	On/Off	From 0 to	From 0 to	2_0_0,
		-∞ dB	-∞ dB	2_0_1,
				2_2_0,
				2_2_1,
				2_1_0,
				3_2_0,
				3_2_1
default	On	-6 dB	-6 dB	3_2_0
value				

Tabela 1 – Korisničke kontrole