

control	Enable	Input gain	Headroo m gain	Output Mode
values	On/Off		From 0 to -∞ dB	2_0_0, 2_0_0, 0_2_0, 0_2_0, 3_2_0
default value	On	-6 dB	-3 dB	2_0_0

Tabela 1 – Korisničke kontrole