

control	Enable	Input gain	Headroo m gain	Output Mode
values	On/Off	From 0 to -∞ dB	From 0 to -∞ dB	2_0_0, 2_0_1, 3_0_0, 3_0_1, 1_2_0, 3_2_0, 3_2_1
default value	On	-6 dB	-6 dB	3_2_0

Tabela 1 – Korisničke kontrole