

control	Enable	Input	Headroo	Output
		gain	m gain	Mode
values	On/Off	From 0 to	From 0 to	2_0_0,
		-∞ dB	-∞ dB	2_0_1,
				0_2_0,
				0_2_1,
				3_2_0
default	On	-6 dB	-3 dB	2_0_0
value				

Tabela I – Korisničke kontrole