Case summary

Birth Date:

Incident ID: 23-01215

Patient ID: 2023011304423800-LP1547543034

Patient Name: Mattox

Patient ID: 2023011304423800-

LP1547543034

Incident ID: <u>23-01215</u> Device ID: <u>MICU 81</u>

Age at Incident: 60 Years Case Start Date: 1/13/2023

Sex: Male Case Start Time: 4:42:39 AM

Race: <u>Unspecified</u> Time Adjustment: <u>System Adjusted Time</u>

Case Summary:

Total Analyses: 1
Total Shocks: 6
Total 12-Leads: 0

Total Time Paced: 00:00:00

Notes:

***Second rhythm check was VT and should have been shocked. Paused compressions for some defib charging. Charge prior to pulse check. Updated at 1/25/2023 1:05:43 AM by zphillips (Zach Phillips). Updated at 1/29/2023 9:02:42 PM by zphillips (Zach Phillips).

Comments:

Table of Contents

CPR reports (by CPR period)	3
CPR report (by CPR period)	3



Device Type: LIFEPAK® 15 Power On: 1/13/2023 4:42:39 AM


CPR Annotations Edited: Yes


Device Configuration: 2D355RO40200UR

*Times have been adjusted by the system.


Duration: 00:50:14 23-01215 Incident ID:

Statistical Parameters: 1000-0300-3000-05






Compression rate




Ventilations/minute




30:07 / 36:21 = 83 %













Device Type: LIFEPAK® 15

Power On: 1/13/2023 4:42:39 AM

CPR Annotations Edited: Yes

Device Configuration: 2D355RO40200UR

*Times have been adjusted by the system.

Duration: 00:50:14 Incident ID: 23-01215

Statistical Parameters: 1000-0300-3000-05

Summary

CPR needed = 36:21 CPR done = 31:18 CPR not done = 5:03 Compression count = 4085 Longest compression pause Pauses over 10 sec = 1:02= 11

Comment

Interval Statistics

CPR period	Responsible for CPR	CPR started	CPR stopped	CPR duration	Pause duration	Reason CPR stopped	Comments	Compr. ratio, %	Compr. rate	Vent. /min
1		00:00:00	00:00:15	00:00:15	00:00:09			62	141	
2		00:00:24	00:02:22	00:01:57	00:00:11			91	148	
3		00:02:33	00:04:26	00:01:53	00:00:18			86	141	
4		00:04:44	00:06:16	00:01:32	00:00:13			88	146	
5		00:06:29	00:09:50	00:03:21	00:00:32			87	127	
6		00:10:21	00:11:41	00:01:19	00:00:11			88	115	
7		00:11:52	00:12:42	00:00:51	00:00:10			84	117	
8		00:12:52	00:22:42	00:09:50	00:00:31			92	144	
9		00:23:13	00:24:00	00:00:47	00:01:02			43	151	
10		00:25:02	00:25:15	00:00:13	00:00:26			33	141	
11		00:25:42	00:26:23	00:00:41	00:00:52			40	105	
12		00:27:15	00:29:30	00:02:15	00:00:24			83	155	
13		00:29:53	00:33:51	00:03:58	00:00:13			91	160	
14		00:34:04	00:36:36	00:02:32	00:00:00			81	163	



Device Type: LIFEPAK® 15

1/13/2023 4:42:39 AM Power On:


CPR Annotations Edited: Yes


Device Configuration: 2D355RO40200UR

*Times have been adjusted by the system.

Duration: 00:50:14 23-01215 Incident ID:

Statistical Parameters: 1000-0300-3000-05







Device Type: LIFEPAK® 15

Power On: 1/13/2023 4:42:39 AM

CPR Annotations Edited: Yes


Device Configuration: 2D355RO40200UR

*Times have been adjusted by the system.

Duration: 00:50:14 Incident ID: 23-01215

Statistical Parameters: 1000-0300-3000-05





[1] Epinephrine, [2] Epinephrine, [3] Epinephrine, [4] Epinephrine, [5] Generic, [6] Generic, [7] Epinephrine, [8] Generic, [9] MAGNESIUM, [10] Epinephrine, [11] Generic

Shock	Time	Energy	Pre-shock CPR pause	Post-shock CPR pause
∳ 1	10:17	200 J	0:27	0:04
§ 2	13:09	200 J	0:00	0:00
∳ 3	17:15	200 J	0:00	0:00
∳ 4	19:51	200 J	0:00	0:00
∳ 5	23:02	200 J	0:20	0:11
∳ 6	29:50	200 J	0:20	0:04