Case summary

Birth Date:

Incident ID: 23-01176

Patient ID: 2023011219400400-LP1547542228

Patient Name: Kelly

Patient ID: 2023011219400400-

LP1547542228

Incident ID: <u>23-01176</u> Device ID: <u>CROZER</u>

Age at Incident: 68 Years Case Start Date: 1/12/2023

Sex: Female Case Start Time: 7:40:04 PM

Race: <u>Unspecified</u> <u>Time Adjustment: System Adjusted Time</u>

Case Summary:

Total Analyses: 0
Total Shocks: 0
Total 12-Leads: 2
Total Time Board: 00:00:0

Total Time Paced: 00:00:00

Notes:

Leads off on multiple occasions. After losing ROSC, need to switch to PADDLES on monitor. Updated at 1/25/2023 12:32:47 AM by zphillips (Zach Phillips).

Comments:

Table of Contents

12-Lead reports	3
12-Lead 1	3
12-Lead 2	4
CPR reports (by CPR period)	5
CPR report (by CPR period)	5

12-Lead 1

 Incident ID:
 23-01176
 Device Type:
 LIFEPAK® 15


 Patient ID:
 2023011219400400-LP1547542228
 Device ID:
 CROZER

 Patient Name:
 Kelly
 Serial Number:
 LP1547542228

 Patient Name:
 Kelly
 Serial Number:
 LP1547542228

 Power On:
 1/12/2023 7:40:04 PM
 Device Configuration:
 2L355RRB0200UR


 Speed/Size:
 25mm/sec/ x1.0
 Software Version:
 3313494-010



12-Lead 2

Incident ID: 23-01176 Device Type: LIFEPAK® 15 Patient ID: 2023011219400400-LP1547542228 Device ID: **CROZER** Serial Number: LP1547542228 Patient Name: Kelly

1/12/2023 7:40:04 PM Device Configuration: 2L355RRB0200UR Power On: Speed/Size: 25mm/sec/ x1.0 Software Version: 3313494-010



Physio-Control, Inc. Comments:

CPR report



Device Type: LIFEPAK® 15
Power On: 1/12/2023 7:40:04 PM


CPR Annotations Edited: Yes


Device Configuration: 2L355RRB0200UR

*Times have been adjusted by the system.


Duration: 00:41:22 Incident ID: 23-01176

Statistical Parameters: 1000-0300-3000-05






Compression rate




Ventilations/minute




6:21 / 7:32 = 84 %



6/minute







CPR report



Device Type: LIFEPAK® 15

Power On: 1/12/2023 7:40:04 PM

CPR Annotations Edited: Yes

Device Configuration: 2L355RRB0200UR

*Times have been adjusted by the system.

Duration: 00:41:22

Incident ID: 23-01176

Statistical Parameters: 1000-0300-3000-05

Summary

 CPR needed
 = 7:32
 CPR done
 = 6:36


 CPR not done
 = 0:56
 Compression count
 = 822

Longest compression pause = 0:23 Pauses over 10 sec = 3

Comment

Interval Statistics

CPR period	Responsible for CPR	CPR started	CPR stopped	CPR duration	Pause duration	Reason CPR stopped	Comments	Compr. ratio, %	Compr. rate	Vent. /min
1		00:00:00	00:01:57	00:01:57	00:00:23			84	128	
2		00:02:20	00:04:16	00:01:56	00:00:12			91	144	2
3		00:04:28	00:05:14	00:00:46	00:00:11			76	132	4
4		00:05:25	00:05:27	00:00:03	00:00:20			85	127	
5		00:05:47	00:06:47	00:01:00	00:00:15			84	125	3
6		00:07:02	00:08:08	00:01:06	00:00:00			92	127	5







CPR report



Device Type: LIFEPAK® 15

Power On: 1/12/2023 7:40:04 PM


CPR Annotations Edited: Yes

Device Configuration: 2L355RRB0200UR

*Times have been adjusted by the system.

Duration: 00:41:22 Incident ID: 23-01176

Statistical Parameters: 1000-0300-3000-05



[1] Epinephrine, [2] Epinephrine

00:07:02