Case summary

Birth Date:

Incident ID: 23-02731

Patient ID: 2023012815490700-LP1547546690

Patient Name: Fraiser

Patient ID: <u>2023012815490700-</u>

LP1547546690

Incident ID: <u>23-02731</u> Device ID: <u>SPARE 1</u>

Age at Incident: 52 Years Case Start Date: 1/28/2023

Sex: Male Case Start Time: 3:49:05 PM

Race: <u>Unspecified</u> Time Adjustment: <u>System Adjusted Time</u>

Notes:

Compression rate over 140 towards the end. Updated at 1/28/2023 10:54:55 PM by zphillips (Zach Phillips).

Comments:

Table of Contents

CPR reports (by CPR period)	3
CPR report (by CPR period)	3

CPR report



Device Type: LIFEPAK® 15 Power On: 1/28/2023 3:49:05 PM


CPR Annotations Edited: Yes


Device Configuration: 2DB55RO40200UR

*Times have been adjusted by the system.


Duration: 00:38:08 Incident ID: 23-02731


Statistical Parameters: 1000-0300-3000-05






Compression ratio







Compression rate






Ventilations/minute







CPR report



Device Type: LIFEPAK® 15

Power On: 1/28/2023 3:49:05 PM

CPR Annotations Edited: Yes

Device Configuration: 2DB55RO40200UR

*Times have been adjusted by the system.

Duration: 00:38:08

Incident ID: 23-02731

Statistical Parameters: 1000-0300-3000-05

Summary

 CPR needed
 = 27:24
 CPR done
 = 25:13

 CPR not done
 = 2:10
 Compression count
 = 2934

Longest compression pause = 0:31 Pauses over 10 sec = 6

Comment

Interval Statistics

CPR period	Responsible for CPR	CPR started	CPR stopped	CPR duration	Pause duration	Reason CPR stopped	Comments	Compr. ratio, %	Compr. rate	Vent. /min
1		00:00:04	00:07:45	00:07:41	00:00:15			90	119	
2		00:08:00	00:09:48	00:01:48	00:00:31			78	114	
3		00:10:19	00:12:20	00:02:00	00:00:10			93	119	
4		00:12:29	00:15:47	00:03:17	00:00:15			93	126	
5		00:16:01	00:20:32	00:04:31	00:00:22			87	122	
6		00:20:54	00:22:31	00:01:37	00:00:16			75	139	
7		00:22:46	00:26:09	00:03:23	00:00:18			88	134	
8		00:26:27	00:27:23	00:00:57	00:00:00			95	148	

CPR report



Device Type: LIFEPAK® 15
Power On: 1/28/2023 3:49:05 PM

CPR Annotations Edited: Yes

Device Configuration: 2DB55RO40200UR

*Times have been adjusted by the system.

Duration: 00:38:08 Incident ID: 23-02731

Statistical Parameters: 1000-0300-3000-05



