Case summary

Birth Date:

Incident ID: 23-03901

Patient ID: 2023020823075900-LP1547542228

Patient Name: Orlando

Patient ID: 2023020823075900-

LP1547542228

Incident ID: <u>23-03901</u> Device ID: <u>CROZER</u>

Age at Incident: 86 Years Case Start Date: 2/8/2023

Sex: Female Case Start Time: 11:08:00 PM

Race: <u>Unspecified</u> <u>Time Adjustment: <u>System Adjusted Time</u></u>

Case Summary:

Total Analyses: 0
Total Shocks: 1
Total 12-Leads: 0
Total Time Paced: 00:00:00

Notes:

\*\*\*Lots of long pauses Rate 155 average

Updated at 3/12/2023 8:25:48 PM by zphillips (Zach Phillips).

Comments:

# **Table of Contents**

CPR reports (by CPR period)	3
CPR report (by CPR period)	3



Device Type: LIFEPAK® 15 Power On: 2/8/2023 11:08:00 PM


CPR Annotations Edited: Yes


Device Configuration: 2L355RRB0200UR

\*Times have been adjusted by the system.


Duration: 00:28:17 23-03901 Incident ID:

Statistical Parameters: 1000-0300-3000-05






Compression rate




Ventilations/minute




16:49 / 22:49 = 74 %



10/minute









Device Type: LIFEPAK® 15

Power On: 2/8/2023 11:08:00 PM

CPR Annotations Edited: Yes

Device Configuration: 2L355RRB0200UR

\*Times have been adjusted by the system.

Duration: 00:28:17

Incident ID: 23-03901

Statistical Parameters: 1000-0300-3000-05

## Summary

CPR needed = 22:49 CPR done = 17:13 CPR not done = 5:37 Compression count = 2490

Longest compression pause Pauses over 10 sec = 13 = 1:10

Comment

#### Interval Statistics

CPR period	Responsible for CPR	CPR started	CPR stopped	CPR duration	Pause duration	Reason CPR stopped	Comments	Compr. ratio, %	Compr. rate	Vent. /min
1		00:00:24	00:02:51	00:02:27	00:00:33			75	179	
2		00:03:24	00:03:30	00:00:06	00:00:11			37	149	
3		00:03:41	00:03:56	00:00:15	00:00:11			58	157	
4		00:04:06	00:05:15	00:01:09	00:00:10			84	158	
5		00:05:26	00:06:29	00:01:03	00:00:22			74	127	1
6		00:06:51	00:07:30	00:00:39	00:00:22			64	129	
7		00:07:52	00:09:24	00:01:32	00:01:10			57	167	1
8		00:10:35	00:12:22	00:01:48	00:00:54			61	159	11
9		00:13:17	00:14:43	00:01:26	00:00:23			79	147	8
10		00:15:06	00:16:07	00:01:01	00:00:09			83	146	11
11		00:16:16	00:18:01	00:01:45	00:00:24			81	167	13
12		00:18:24	00:19:47	00:01:23	00:00:11			88	144	15
13		00:19:58	00:21:10	00:01:12	00:00:11			87	135	18
14		00:21:21	00:22:51	00:01:30	00:00:00			99	138	18



Device Type: LIFEPAK® 15
Power On: 2/8/2023 11:08:00 PM


CPR Annotations Edited: Yes


Device Configuration: 2L355RRB0200UR

\*Times have been adjusted by the system.

Duration: 00:28:17 Incident ID: 23-03901

Statistical Parameters: 1000-0300-3000-05







Device Type: LIFEPAK® 15

Power On: 2/8/2023 11:08:00 PM


CPR Annotations Edited: Yes

Device Configuration: 2L355RRB0200UR

\*Times have been adjusted by the system.

Duration: 00:28:17 Incident ID: 23-03901

Statistical Parameters: 1000-0300-3000-05



#### [1] Epinephrine, [2] Epinephrine, [3] Epinephrine, [4] Intubation

Shock	Time	Energy	Energy Pre-shock CPR pause	
<b>∳</b> 1	0:42	360 J	0:00	0:00