Case summary

Birth Date:

Incident ID: 23-04301

Patient ID: 2023021207152900-LP1547545197

Patient Name: Kaladjian

Patient ID: <u>2023021207152900-</u>

LP1547545197

Incident ID: <u>23-04301</u>

Device ID: MICU 66

Age at Incident: 74 Years

Case Start Date: <u>2/12/2023</u>

Sex: <u>Male</u>

Case Start Time: 7:15:28 AM

Race: <u>Unspecified</u> Time Adjustment: <u>System Adjusted Time</u>

Case Summary:

Total Analyses: 0
Total Shocks: 3
Total 12-Leads: 0
Total Time Paced: 00:00:00

Total Time Faceu. 00.00.0

Notes:

Comments:

Table of Contents

CPR reports (by CPR period)	3
CPR report (by CPR period)	3



Device Type: LIFEPAK® 15
Power On: 2/12/2023 7:15:28 AM


CPR Annotations Edited: Yes


Device Configuration: 2L355RO40200UR

*Times have been adjusted by the system.


Duration: 00:54:22 Incident ID: 23-04301

Statistical Parameters: 1000-0300-3000-05






Compression rate




Ventilations/minute




40:13 / 46:04 = 87 %



10/minute







Device Type: LIFEPAK® 15

Power On: 2/12/2023 7:15:28 AM

CPR Annotations Edited: Yes

Device Configuration: 2L355RO40200UR

*Times have been adjusted by the system.

Duration: 00:54:22 Incident ID: 23-04301

Statistical Parameters: 1000-0300-3000-05

Summary

CPR needed	= 46:04	CPR done	= 40:33
CPR not done	= 5:31	Compression count	= 5047
Longest compression pause	= 0:56	Pauses over 10 sec	= 13
Comment			



Device Type: LIFEPAK® 15
Power On: 2/12/2023 7:15:28 AM

CPR Annotations Edited: Yes

Device Configuration: 2L355RO40200UR

*Times have been adjusted by the system.

Duration: 00:54:22 Incident ID: 23-04301

Statistical Parameters: 1000-0300-3000-05

Interval Statistics

CPR period	Responsible for CPR	CPR started	CPR stopped	CPR duration	Pause duration	Reason CPR stopped	Comments	Compr. ratio, %	Compr. rate	Vent. /min
1		00:00:00	00:00:03	00:00:03	00:00:14			16	123	
2		00:00:17	00:00:24	00:00:07	00:00:06			70	120	
3		00:00:30	00:00:51	00:00:21	00:00:40			92	119	
4		00:01:31	00:03:00	00:01:29	00:00:16			87	117	
5		00:03:16	00:06:46	00:03:31	00:00:07			97	129	
6		00:06:53	00:08:42	00:01:49	00:00:10			91	130	
7		00:08:53	00:10:51	00:01:58	00:00:21			85	127	2
8		00:11:12	00:11:26	00:00:14	00:00:06			87	135	
9		00:11:31	00:14:06	00:02:35	00:00:20			88	134	2
10		00:14:27	00:14:34	00:00:07	00:00:04			71	140	
11		00:14:38	00:16:18	00:01:40	00:00:56			64	120	6
12		00:17:14	00:18:12	00:00:58	00:00:02			100	120	3
13		00:18:14	00:18:47	00:00:33	00:00:17			66	121	7
14		00:19:03	00:21:31	00:02:27	00:00:11			90	111	11
15		00:21:42	00:24:23	00:02:42	00:00:30			84	123	8
16		00:24:53	00:25:09	00:00:16	00:00:04			83	130	
17		00:25:13	00:25:18	00:00:05	00:00:06			54	125	
18		00:25:24	00:28:20	00:02:56	00:00:18			89	139	15
19		00:28:38	00:29:00	00:00:22	00:01:39			61	140	17
20		00:30:39	00:32:09	00:01:30	00:00:09			88	133	8
21		00:32:18	00:32:59	00:00:41	00:00:20			68	135	4
22		00:33:19	00:34:29	00:01:11	00:00:11			86	138	12
23		00:34:41	00:38:18	00:03:37	00:00:08			93	136	10
24		00:38:26	00:41:12	00:02:47	00:00:10			94	116	14



Device Type: LIFEPAK® 15
Power On: 2/12/2023 7:15:28 AM

CPR Annotations Edited: Yes

Device Configuration: 2L355RO40200UR


*Times have been adjusted by the system.

Duration: 00:54:22 Incident ID: 23-04301


Statistical Parameters: 1000-0300-3000-05

Interval Statistics

CPR period	Responsible for CPR	CPR started	CPR stopped	CPR duration	Pause duration	Reason CPR stopped	Comments	Compr. ratio, %	Compr. rate	Vent. /min
25		00:41:22	00:43:46	00:02:24	00:00:05			97	144	14
26		00:43:50	00:45:00	00:01:09	00:00:05			93	131	11
27		00:45:05	00:46:47	00:01:42	00:00:07			88	141	14
28		00:46:54	00:48:14	00:01:20	00:00:00			99	129	28



CPR QUIK-VIEW





Device Type: LIFEPAK® 15
Power On: 2/12/2023 7:15:28 AM

CPR Annotations Edited: Yes


Device Configuration: 2L355RO40200UR

*Times have been adjusted by the system.

Duration: 00:54:22 Incident ID: 23-04301

Statistical Parameters: 1000-0300-3000-05







Device Type: LIFEPAK® 15
Power On: 2/12/2023 7:15:28 AM

CPR Annotations Edited: Yes


Device Configuration: 2L355RO40200UR

*Times have been adjusted by the system.

Duration: 00:54:22 Incident ID: 23-04301

Statistical Parameters: 1000-0300-3000-05





[1] EPINEPHRINE 10, [2] EPINEPHRINE 10, [3] Generic, [4] EPINEPHRINE 10, [5] EPINEPHRINE 10, [6] EPINEPHRINE 10

Shock	Time	Energy	Pre-shock CPR pause	Post-shock CPR pause
§ 1	0:27	360 J	0:03	0:03
9 2	3:12	360 J	0:12	0:04
§ 3	11:28	360 J	0:02	0:04