

		FIR	
Product Code	DL545	Centralised ID	DTIL25030029
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	24-03-2025

SL No.	Description	Details
1	Service Request Number	DTIL25030029
2	Date of communication failure	2024-08-31 16:28:00
3	Device Model	DL545
4	Defective device PSN	2210282003
5	VIN Number	MB1PREHD8PENJ9019
6	Device IMEI	867624067659747
7	Device CCID	916420534722685000
8	Date of Sale of Device	28-10-2022
9	S Trigger Date	12-01-2023
10	C Trigger Date	17-01-2023
11	Commercial Expiry date	14-04-2027
12	Active Profile (BSNL/Airtel/Dual)	Airtel
13	Vehicle Type / Model	Passenger
14	Failure Location Plant/ Field- Customer Address	KERALA
15	Kilometers/Hours	Kilometers
16	Main Battery Voltage	25.45
17	Service Engineer Name	Arun
18	Reason for Replacement/Repair	Repair
19	Dealer Location	KADAPA VEDURURU
20	Darby Last communication date	2024-08-31 16:28:00
21	Device Replacement request Initiation date	2025-03-24 06:18:57
22	Returnable / Non-Returnable	Repair

Approved By:	Name	Date	Signature
Initiated by- Service Eng.	Arun	24-03-2025	Arun
Service Manager	upendram	N/A	upendram
Sales & Service Head	Rajendran Subramanian	N/A	