



FIR

Product Code	DL545	Centralised ID	DTIL25030031
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	25-03-2025

SL No.	Description	Details
1	Service Request Number	DTIL25030031
2	Date of communication failure	2025-03-20 11:25:00
3	Device Model	DL545
4	Defective device PSN	2210142101
5	VIN Number	MB1PREHD4NEPJ8503
6	Device IMEI	867624067662782
7	Device CCID	8.99164205347226e+19
8	Date of Sale of Device	14-10-2022
9	S Trigger Date	13-12-2022
10	C Trigger Date	15-03-2023
11	Commercial Expiry date	09-03-2027
12	Active Profile (BSNL/Airtel/Dual)	Dual
13	Vehicle Type / Model	Passenger
14	Failure Location Plant/ Field- Customer Address	KERALA
15	Kilometers/Hours	Kilometers
16	Main Battery Voltage	24.8
17	Service Engineer Name	Arun
18	Reason for Replacement/Repair	Repair
19	Dealer Location	TVS Vehicle Mobility Solution Pvt Ltd ■ Musaliyar complex ■ 2nd Milestone ■ Kilikollor ,Kollam
20	Darby Last communication date	2025-03-20 11:25:00
21	Device Replacement request Initiation date	2025-03-25 11:36:09
22	Returnable / Non-Returnable	Repair

Approved By:	Name	Date	Signature
Initiated by- Service Eng.	Arun	25-03-2025	Arun
Service Manager	Eliyas	N/A	upendram
Sales & Service Head	Rajendran Subramanian	N/A	