

		FIR	
Product Code	DL545	Centralised ID	DTIL25030032
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	25-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030032	
2	Date of communication failure	2025-02-26 05:13:00	
3	Device Model	DL545	
4	Defective device PSN	2210312154	
5	VIN Number	MB1PREHDXNEPJ8795	
6	Device IMEI	867624068939809	
7	Device CCID	8.991642053472267e+19	
8	Date of Sale of Device	31-10-2022	
9	S Trigger Date	15-12-2022	
10	C Trigger Date	15-03-2023	
11	Commercial Expiry date	09-03-2027	
12	Active Profile (BSNL/Airtel/Dual)	Dual	
13	Vehicle Type / Model	Passenger	
14	Failure Location Plant/ Field- Customer Address	KERALA	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	25.35	
17	Service Engineer Name	Arun	
18	Reason for Replacement/Repair	Repair	
19	Dealer Location	ASSISTANT TRANSPORT OFFICER, ■ KSRTC, PARASSALA.	
20	Darby Last communication date	2025-02-26 05:13:00	
21	Device Replacement request Initiation date	2025-03-25 11:54:12	
22	Returnable / Non-Returnable	Repair	
Approved By:		Name	Signature
Initiated by- Service Eng.		Arun	Arun
Service Manager		Eliyas	upendram
Sales & Service Head		Rajendran Subramanian	.