

		FIR	
Product Code	DL545	Centralised ID	DTIL25030034
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	26-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030034	
2	Date of communication failure	2024-01-07 09:15:00	
3	Device Model	DL545	
4	Defective device PSN	2202041300	
5	VIN Number	MB1TZKHD6NPJR760	
6	Device IMEI	867624060072062	
7	Device CCID	8.991649063462242e+19	
8	Date of Sale of Device	05-02-2022	
9	S Trigger Date	21-04-2022	
10	C Trigger Date	08-01-2023	
11	Commercial Expiry date	03-03-2023	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	N/A	
14	Failure Location Plant/ Field- Customer Address	ASSAM	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	26.38	
17	Service Engineer Name	Arun	
18	Reason for Replacement/Repair	Repair	
19	Dealer Location		
20	Darby Last communication date	2024-01-07 09:15:00	
21	Device Replacement request Initiation date	2025-03-26 02:47:09	
22	Returnable / Non-Returnable	Repair	
Approved By:		Name	Date
Initiated by- Service Eng.		Arun	26-03-2025
Service Manager		Eliyas	.
Sales & Service Head		Rajendran Subramanian	.