

		FIR	
Product Code	DL545	Centralised ID	DTIL25030036
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	26-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030036	
2	Date of communication failure	2023-03-27 15:23:00	
3	Device Model	DL545	
4	Defective device PSN	2112221093	
5	VIN Number	MB1TZKHD6NPLR1667	
6	Device IMEI	867624060041810	
7	Device CCID	8.991649063462643e+19	
8	Date of Sale of Device	24-12-2021	
9	S Trigger Date	13-03-2022	
10	C Trigger Date	25-05-2022	
11	Commercial Expiry date	28-02-2026	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	T&T	
14	Failure Location Plant/ Field- Customer Address	GANDHI DHAM	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	25.0	
17	Service Engineer Name	Arun Maity	
18	Reason for Replacement/Repair	Repair	
19	Dealer Location	WM-Pritam-9099919446 ASL MOTORS (GALPADAR GANDHI	
20	Darby Last communication date	2023-03-27 15:23:00	
21	Device Replacement request Initiation date	2025-03-26 04:35:51	
22	Returnable / Non-Returnable	Repair	
Approved By:		Name	Date
Initiated by- Service Eng.		Arun Maity	26-03-2025
Service Manager		Kunal	.
Sales & Service Head		Rajendran Subramanian	.