

		FIR	
Product Code	DL548	Centralised ID	DTIL25030038
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	26-03-2025

SL No.	Description	Details
1	Service Request Number	DTIL25030038
2	Date of complaint	26-03-2025
3	Complaint Raised By	Dealer
4	Complaint Raised Name	Rajesh motors -Ramchandrapura Jaipur
5	Contact Number	9414061730
6	Complaint Raised Through	Telephone
7	Service Engineer Name	Arun Maity
8	Device Model	DL548
9	Device PSN	2408057125
10	VIN Number	MB1H3LHD9RRGZ4937
11	Firmware	G130M153
12	Configuration	Operational Mode
13	Device IMEI	867950076206703
14	Device ICCID	8.991643124482294e+19
15	Date of Sale of Device	19-08-2024
16	Telco Status	Commercial
17	Active Profile	Airtel
18	S Trigger Date	04-09-2024
19	Commercial Expiry Date	29-10-2025
20	First communication in Darby	2024-09-02 03:14:00
21	Last communication in Darby	2025-01-02 05:39:00
22	Vehicle support Date	26-03-2025
23	Vehicle sale Date	14-10-2022
24	Vehicle Running Location	BHAKROTA-JAIPUR
25	Kilometers/Hours	Kilometers
26	Vehicle Run	8249
27	Main Battery Voltage	25.0
28	Issue Identified	Not Powering ON
29	Issue Analysis	Power issue
30	External Modification	Others

31	Issue Description	Got vehicle support and found device having m153 sw with pow	
32	Engineer Recommendation	Repair	
33	Device sent to	Goa	
34	Dealer Location		
35	Manager Remarks		
36	HOD Remarks		
Approved By:		Name	Signature
Initiated by- Service Eng.		Arun Maity	Arun Maity
Service Manager		Kunal	.
Sales & Service Head		Rajendran Subramanian	.