

		FIR	
Product Code	DL545	Centralised ID	DTIL25030030
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	24-03-2025

SL No.	Description	Details
1	Service Request Number	DTIL25030030
2	Date of communication failure	2025-03-24 03:02:00
3	Device Model	DL545
4	Defective device PSN	2211232027
5	VIN Number	MB1NECHD0PPNU8204
6	Device IMEI	867624067730704
7	Device CCID	916420534722293000
8	Date of Sale of Device	04-02-2023
9	S Trigger Date	03-04-2023
10	C Trigger Date	03-04-2023
11	Commercial Expiry date	06-05-2027
12	Active Profile (BSNL/Airtel/Dual)	Dual
13	Vehicle Type / Model	Haulage
14	Failure Location Plant/ Field- Customer Address	ODISHA TO WESTBENGAL
15	Kilometers/Hours	Kilometers
16	Main Battery Voltage	24.0
17	Service Engineer Name	Arun Maity
18	Reason for Replacement/Repair	Replace
19	Dealer Location	WM-Surajit Bera-9836282464■ Shree Automotive-Kolkata■ NH-6, Junglpur, PO: Argora Junglepur, Howrah Junglepur, WES
20	Darby Last communication date	2025-03-24 03:02:00
21	Device Replacement request Initiation date	2025-03-24 09:45:59
22	Returnable / Non-Returnable	Replace

Approved By:	Name	Date	Signature
Initiated by- Service Eng.	Arun Maity	24-03-2025	Arun Maity
Service Manager	upendram	N/A	upendram
Sales & Service Head	Rajendran Subramanian	N/A	