

		FIR	
Product Code	DL545	Centralised ID	DTIL25030035
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	26-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030035	
2	Date of communication failure	2025-03-25 03:19:00	
3	Device Model	DL545	
4	Defective device PSN	2202171290	
5	VIN Number	MB1NGCHD2NPKR6463	
6	Device IMEI	867624060758769	
7	Device CCID	8.991649063462235e+19	
8	Date of Sale of Device	19-02-2022	
9	S Trigger Date	30-03-2022	
10	C Trigger Date	13-04-2022	
11	Commercial Expiry date	25-06-2025	
12	Active Profile (BSNL/Airtel/Dual)	Dual	
13	Vehicle Type / Model	N/A	
14	Failure Location Plant/ Field- Customer Address	RAIPUR TO JAMSHADPUR	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	25.47	
17	Service Engineer Name	Arun Maity	
18	Reason for Replacement/Repair	Replace	
19	Dealer Location		
20	Darby Last communication date	2025-03-25 03:19:00	
21	Device Replacement request Initiation date	2025-03-26 02:47:53	
22	Returnable / Non-Returnable	Replace	
Approved By:		Name	Signature
Initiated by- Service Eng.		Arun Maity	Arun Maity
Service Manager		Eliyas	.
Sales & Service Head		Rajendran Subramanian	.