

		FIR	
Product Code	DL545	Centralised ID	DTILDC-25091436
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	2025-09-30 15:05:00

SL No.	Description	Details
1	Service Request Number	DTILDC-25091436
2	Date of Complaint	2025-09-30 15:05:00
3	Complaint Raised By	AMPL KOMPALLY
4	Contact Number	7659025219
5	Complaint Raised Through	Mail
6	Service Engineer Name	Gayadhar
7	Device Model	DL545
8	PSN	2210081103
9	VIN Number	MB1ASEHDSNABN1262
10	Firmware Version	F6b4
11	Device IMEI	867624067665702
12	Device ICCID	89916420534722604957
13	Date of Sale of Device	2022-12-14
14	Telco Status	Commercial
15	Active Profile	--
16	Commercial Expiry Date	2026-01-17 05:30:00
17	First communication in Darby	2022-11-11 13:59:00
18	Last communication in Darby	2025-09-26 10:32:00
19	Vehicle Running Location	ALL INDIA
20	Vehicle Run	Kilometers
21	Kilometers/Hours	206351
22	Main Battery Voltage	26.33
23	Issue Identified	NRD
24	Issue_analysis	VIC Issue
25	External Modification	No
26	Issue Description	VIC LED on, USB ports not coming, Device sent to our office for analysis
27	Engineer Recommendation	Replace_Repair
28	Device Sent To	Hyderabad

29	Dealer Address	Mr. Anannd ■ AMPL KOMPALLY ■ 4-7 7, Survey no 173 to 175 & 156 ompally. ■ Quthubullapur (Manda l), Kompally-500014, Telengana , India. ■ Mobile no - 99890182 22/08418-233370/71/72	
30	Final Action Taken	VIC LED on, USB ports not coming, Device sent to our office for analysis	
31	Manager Comments		
32	HOD Comments	Replace_Repair	
Approved By:		Name	Signature
Service Engineer		Gayadhar	2025-09-30 15:05:00
Manager		Kunal	2025-09-30 21:05:38
Sales & Service Head		Rajendran Subramanian	2025-09-30 21:05:38 