

		FIR	
Product Code	DL548	Centralised ID	DTILDC-25071228
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	2025-07-11 23:07:00

SL No.	Description	Details
1	Service Request Number	DTILDC-25071228
2	Date of Complaint	2025-07-11 23:07:00
3	Complaint Raised By	Dubey
4	Contact Number	7992330514
5	Complaint Raised Through	Telephone
6	Service Engineer Name	Gayadhar
7	Device Model	DL548
8	PSN	2505138043
9	VIN Number	G45FES12345678901
10	Firmware Version	G131b15425
11	Device IMEI	864524076794860
12	Device ICCID	89916450244842660722
13	Date of Sale of Device	N/A
14	Telco Status	Bootstrap
15	Active Profile	--
16	Commercial Expiry Date	2025-11-04 05:30:00
17	First communication in Darby	N/A
18	Last communication in Darby	N/A
19	Vehicle Running Location	N/A
20	Vehicle Run	Kilometers
21	Kilometers/Hours	0
22	Main Battery Voltage	24.0
23	Issue Identified	Not Powering ON
24	Issue_analysis	Device Not Powering ON
25	External Modification	No
26	Issue Description	Device need to be sent to analysis
27	Engineer Recommendation	Replace
28	Device Sent To	Hyderabad

29	Dealer Address	Gayadhar Malik ■ House no- E17 ■ Kaushalya Enclave phase 1, Ga ngapur road, ■ Rudrapur, UTK - 263153 ■ Mobile No - 9045096146	
30	Final Action Taken	Device need to be sent to anal ysis	
31	Manager Comments		
32	HOD Comments	Replace	
Approved By:		Name	Signature
Service Engineer		Gayadhar	2025-07-11 23:07:00
Manager		Kunal	2025-07-12 20:09:18
Sales & Service Head		Rajendran Subramanian	2025-07-12 20:09:18