

		FIR	
Product Code	DL548	Centralised ID	DTILDC-25071228
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	2025-07-11 23:07:00

SL No.	Description	Details
1	Service Request Number	DTILDC-25071228
2	Date of Complaint	2025-07-11 23:07:00
3	Complaint Raised By	Dubey
4	Contact Number	7992330514
5	Complaint Raised Through	Telephone
6	Service Engineer Name	Gayadhar
7	Device Model	DL548
8	PSN	2505138043
9	VIN Number	G45FES12345678901
10	Firmware Version	G131b15425
11	Device IMEI	864524076794860
12	Device ICCID	89916450244842660722
13	Date of Sale of Device	N/A
14	Telco Status	Bootstrap
15	Active Profile	--
16	Commercial Expiry Date	2025-11-04 05:30:00
17	First communication in Darby	N/A
18	Last communication in Darby	N/A
19	Vehicle Running Location	N/A
20	Vehicle Run	Kilometers
21	Kilometers/Hours	0
22	Main Battery Voltage	24.0
23	Issue Identified	Not Powering ON
24	Issue_analysis	Device Not Powering ON
25	External Modification	No
26	Issue Description	Device need to be sent to analysis
27	Engineer Recommendation	Replace_Repair
28	Device Sent To	Hyderabad

29	Dealer Address	Gayadhar Malik■ House no- E17■ Kaushalya Enclave phase 1, Ga ngapur road,■ Rudrapur, UTK - 263153■ Mobile No - 9045096146	
30	Final Action Taken	Device need to be sent to anal ysis	
31	Manager Comments		
32	HOD Comments	Replace_Repair	
Approved By:		Name	Signature
Service Engineer		Gayadhar	Gayadhar
Manager		Kunal	Kunal
Sales & Service Head		Rajendran Subramanian	