

		FIR	
Product Code	DL545	Centralised ID	DTIL25030026
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	21-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030026	
2	Date of communication failure	2025-03-12 05:58:00	
3	Device Model	DL545	
4	Defective device PSN	2407047122	
5	VIN Number	MB1TSKHD3PRFM5881	
6	Device IMEI	564324567890876	
7	Device CCID	8991643013472648270	
8	Date of Sale of Device	28-02-2025	
9	S Trigger Date	N/A	
10	C Trigger Date	N/A	
11	Commercial Expiry date	14-03-2025	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	N/A	
14	Failure Location Plant/ Field- Customer Address	UTTARPRADESH	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Siva	
18	Reason for Replacement/Repair	Repair	
19	Darby Last communication date	2025-03-12 05:58:00	
20	Device Replacement request Initiation date	2025-03-21 05:59:03	
21	Returnable / Non-Returnable	Repair	
Approved By:		Name	Date
Initiated by- Service Eng.		Siva	21-03-2025
Service Manager		upendram	N/A
Sales & Service Head		Rajendran Subramanian	N/A

