

		FIR	
Product Code	DL545	Centralised ID	DTIL25030028
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	21-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030028	
2	Date of communication failure	2024-07-01 05:51:00	
3	Device Model	DL545	
4	Defective device PSN	2207111151	
5	VIN Number	MB1PREHD1NEPJ8555	
6	Device IMEI	867624067344340	
7	Device CCID	916420534722332000	
8	Date of Sale of Device	11-07-2022	
9	S Trigger Date	28-12-2022	
10	C Trigger Date	17-03-2023	
11	Commercial Expiry date	17-03-2023	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	Passenger	
14	Failure Location Plant/ Field- Customer Address	KERALA	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.67	
17	Service Engineer Name	Arun	
18	Reason for Replacement/Repair	Repair	
19	Darby Last communication date	2024-07-01 05:51:00	
20	Device Replacement request Initiation date	2025-03-21 13:59:14	
21	Returnable / Non-Returnable	Repair	
Approved By:		Name	Date
Initiated by- Service Eng.		Arun	21-03-2025
Service Manager		upendram	N/A
Sales & Service Head		Rajendran Subramanian	N/A

