



FIR

Product Code	Anil	Centralised ID	DTIL25030039
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	26-03-2025

SL No.	Description	Details
1	Service Request Number	DTIL25030039
2	Date of complaint	08-01-2000
3	Complaint Raised By	--
4	Complaint Raised Name	Rajesh mtoros -Ramchandrapura Jaipur
5	Contact Number	9414061730
6	Complaint Raised Through	--
7	Service Engineer Name	--
8	Device Model	Anil
9	Device PSN	2408057125
10	VIN Number	MB1H3LHD9RRGZ4937
11	Firmware	G130M153
12	Configuration	--
13	Device IMEI	N/A
14	Device ICCID	8.991643124482294e+19
15	Date of Sale of Device	N/A
16	Telco Status	--
17	Active Profile	--
18	S Trigger Date	N/A
19	C Trigger Date	N/A
20	Commercial Expiry Date	N/A
21	First communication in Darby	N/A
22	Last communication in Darby	N/A
23	Vehicle support Date	N/A
24	Vehicle sale Date	N/A
25	Vehicle Running Location	BHAKROTA-JAIPUR
26	Kilometers/Hours	Kilometers
27	Vehicle Run	8249
28	Main Battery Voltage	24.0
29	Issue Identified	Not Powering ON
30	Issue Analysis	--

31	External Modification			
32	Issue Description		Got vehicle support and found device having m153 sw with pow	
33	Engineer Recommendation		Repair	
34	Device sent to		Goa	
35	Dealer Location			
36	Manager Remarks			
37	HOD Remarks			
Approved By:		Name	Date	Signature
Initiated by- Service Eng.		--	26-03-2025	--
Service Manager		Kunal	2025-03-26 23:54:34	upendram
Sales & Service Head		Rajendran Subramanian	2025-03-26 23:54:50	